RICOH

Technical Bulletin

PAGE: 1/1

| Model: Ap-C3 Date: 06-Jan-14 |
|------------------------------|
|------------------------------|

| Subject: Missing Parts number for Ap-C3 DF3070 | | Prepared by: Y.Saitoh | | | |
|--------------------------------------------------------|-------------------|-----------------------|------|---------------------------|--|
| From: 2nd Tech Service Sect., MFP/P Tech Service Dept. | | | | | |
| Classification: | ☐ Troubleshooting | □ Part informa | tion | Action required | |
| | ☐ Mechanical | ☐ Electrical | | ☐ Service manual revision | |
| | ☐ Paper path | ☐ Transmit/red | eive | ☐ Retrofit information | |
| | ☐ Product Safety | Other (|) | ☐ Tier 2 | |

Change/Reason: The following was missing from the Parts Catalog.

| Part | Description | Q'ty | Int | Page | Index | Note |
|----------|------------------------------|------|-----|------|-------|------|
| number | | | | | | |
| D6304143 | GUIDE PLATE:COVER:PAPER FEED | 1 | | 4 | 27* | |

^{*}New Index

2.Original Feed 1 (D630)

