## Modification Bulletin

#### **PAGE: 1/1**

Model: Kir-C2 ARE	DF (DF79)	ate: 4-Jul-0	6	No.: MB617001					
Modified Article:	Belt Unit		Prepared by: S. Tomoe						
From: 1st Tech. Su	pport Sec. Service Support D								
Reason for	□ Parts catalog correction	U Vendor	cha	ange	Other				
Modification:	To facilitate assembly	ove	e reliability		neet standards				
	Part standardization Produ			afety	(RoHs compliant)				

Old part number	New part number	Description		Int	Page	Index	Note
A8592100	B3862105	Belt Unit: Paper Feed: Ass'y		X/O	7	38	1

**Change:** The materials for these parts were changed. **Reason:** To comply with the RoHS Directive.

Note: The functions of these parts were not changed.

#### **IMPORTANT:**

RICOH

• The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: Parts with the **new** P/N: **Non-RoHS** compliant parts **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
<b>RoHS</b> Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	ОК	OK

• **Continue using** non-RoHS compliant parts on non-ROHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.

• **DO NOT use** <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines. **Note:** This is to make sure that all machines are in full compliance with the RoHS Directive.

### RICOH

### Modification Bulletin

Reissued: 30-Mar-07

Model: DF79

Date: 9-Nov-06

No.: MB617002a

#### **MB** Reissue

The items in *bold italics* were corrected or added.

Modified Article:	PCB Main Control	Prepared by: Y.Murata					
From: 1st Tech. Su	pport Sec. Service Support I						
Reason for	Parts catalog correction	Vendor ch	ange	Other			
Modification:	To facilitate assembly	To improve	e reliability	To meet standards			
	Part standardization	Product Sa	afety	()			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number		_		_		
B6175500	B6175510	PCB Main Control	1	X/O	13	8	
B6175510 🖌	B6175520	PCB Main Control	1	0/0	13	8	

**Change:** CPU has been changed. **Reason:** Vender has been changed.

## Modification Bulletin

#### **PAGE: 1/1**

Model: DF79		ate: 9-Nov-	06	No.: MB617003				
Modified Article:	PCB Main Control	Prepared by: Y.Murata						
From: 1st Tech. Su	pport Sec. Service Support D							
Reason for	Parts catalog correction	🛛 Vendor	cha	ange	Other			
Modification:	To facilitate assembly	🗌 To impro	ove	e reliability	To meet standards			
	Part standardization Product			afety				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B6175510	B6175520	PCB Main Control	1	X/O	13	8	

**RICOH** 

**Change:** The CPU has changed. **Reason:** Because the vendor has been changed.

# **RICOH** Part Change Information List

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC Page	Inde	ex Set	Set Int	RTB	
K-C2 ARDF (DF79)	B617	201003		B6175703	C6825703	HARNESS:STEPPER MOTOR	1	1	0/0	13	2	26			

Note	Ref. Nr.	ECN Nr.
	V0902896	

#### **RICOH** Part Change Information List

Date: October 29, 2010

Model	Codo P	CIL Nr.	PCIL	Old part	New part	Description	014 015	New Q'ty	Int	3DPC	Page Inde	av Cat	Sot Int	RTB	Note	Ref. Nr.	ECN Nr.
Woder	Code P	OIL NI.	Correction	number	number	Description	Old Q ly	New Gity		5010	rage mus		OCT IIII	mb	NO(G	Hel. NI.	LON NI.
ARDF (DF79)	B617 2	201010		A8592166	B8303504	TIMING BELT - 40S2M100	1	1	0/0		7 :	32				V1001384	