

Model: Cattleya E-700 Controller		Date: 11-Dec-00	No.: MG936001
Modified Article: Spare Part Number Changes		Prepared by: Chisato Tsuji	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G9365020	G9385020	128MB DIMM	1	O/O	3	4	
G9365081	G9365092	USER SOFTWARE CD	1	O/O	3	12	
G9369500	G9369501	SERVICE KIT (SYSTEM CD)	1	O/O	3	14	
G9369850	G9369851	E-700 SERVICE MANUAL - ENGLISH	1	O/O	3	15	

The P/N for the above items have been changed in accordance with P/N standardization at EFI. The contents of these items have not changed, except for the Service Kit (formerly the System CD), which now contains the system software installation manual and CD.

Model: Cattleya E-700 Controller		Date: 20-Jun-02	No.: MG936002
Modified Article: E-700 Spare Parts Added (BIOS ROM)		Prepared by: Chisato Tsuji	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following item has been newly registered as a spare part.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G9385136	BIOSROM:X3E:RICOH:45019962	1	-	-	-	-

Note: When replacing the motherboard, the BIOS ROM can be removed from the old board and attached to the new board. Please order this part when it is lost or defective.