(GO	ПЛ
いいいり	Inl

Modification **B**ulletin

in	PAGE: 1/1

Model: Cattleya2 Controller E-810/E-820			Date	e: 23-Aug-0	2	No.: MG940001		
Modified Article: E		Prepared by: Chisato Tsuji						
From: Technical Services sec. Service Planning Dept.								
Reason for	□ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		()			
	☐ Part standardization	☐ Othe	r					

Please apply the following P/N correction to your Parts Catalogs (E-810/E-820).

Incorrect	Correct	Description	Q'ty	Int	Page	Index	Note
part number	part number						
A7475282	A7245282	Grayscale Strip	1	-	4	7	

വത്ത	吅
]GO	ய

Modification **B**ulletin

PAGE: 1/1

Model: Cattleya2 Controller E-810/E-820			Date	e: 16-Oct-02	2	No.: MG940002		
Modified Article: E-820 Parts Catalog Correction				Prepared by: Chisato Tsuji				
From: Technical Services sec. Service Planning Dept.								
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To n	neet standards			
Modification:	☐ To facilitate assembly	☐ To improve reliability		()			
	☐ Part standardization	☐ Othe	r					

Please correct your E-820 parts catalog as follows:

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G9409510	G9409501	Service Kit	1	O/O	4	6	
G9405182	G9406112	User Software CD	1	O/O	4	4	