



Part Change Information List

Date: November 30, 2009

| Model                     | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description            | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|---------------------------|------|----------|-----------------|-----------------|-----------------|------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| Printer Controller EB-135 | D847 | 200911   |                 | D3801053        | D4501053        | DECAL:FIERY:SERVER:ENG | 1        | 1        | O/O |      | 2    | 21    |     |         |     |      | V0902925 | 9110085 |



Part Change Information List

Date: November 30, 2012

| Model                          | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description                    | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr.             | ECN Nr. |
|--------------------------------|------|----------|-----------------|-----------------|-----------------|--------------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------------------|---------|
| B-C3 Printer Controller EB-135 | G847 | 201211   |                 | 5K530257        | D5021020        | HDD:DEPOPULATED:80GB:SUB-ASS'Y | 1        | 1        | O/O |      | 3    | 9     |     |         |     |      | V1201522<br>V1203119 |         |
| B-C3 Printer Controller EB-135 | G847 | 201211   |                 | 5K53 0255       | 5K530257        | HDD:HDS721680PLA380:ROHS       | 1        | 1        | O/O |      | 3    | 9     |     |         |     |      | V0800375             |         |

| Model          | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description       | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|----------------|------|-------------|-----------------|-----------------|-----------------|-------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| EFI-B(DOM/EXP) | G847 | 201501      |                 | 5K530031        | D5023031        | PANEL:SIDE:ASS'Y  | 1        | 1        | O/O |      | 3    | 8     |     |         |     |      | V1403887   |            |
| EFI-B(DOM/EXP) | G847 | 201501      |                 | 5K530033        | D6503033        | BRACKET:PCI:BLANK | 1        | 1        | O/O |      | 3    | 29    |     |         |     |      | V1403887   |            |



## Part Change Information List

Date: March 3, 2017

| Model          | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description            | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|----------------|------|-------------|-----------------|-----------------|-----------------|------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| EFI-B_DOM_EXP_ | G847 | 201702      |                 | D4501053        | D3BN1053        | DECAL:FIERY:SERVER:ENG | 1        | 1        | O/O | N    | 3    | 21    |     |         |     |      | V1603853   | 16111135   |



## Part Change Information List

Date: May 12, 2017

| Model                            | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description     | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|----------------------------------|------|-------------|-----------------|-----------------|-----------------|-----------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| Katana-C1 Printer Contrlr EB-135 | G847 | 201704      |                 | D5023031        | D6503031        | PANEL:SIDE:ASSY | 1        | 1        | O/O | N    | 2    | 8     |     |         |     |      | V1700644   |            |



## Part Change Information List

Date: November 2, 2017

| Model         | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description                     | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|---------------|------|-------------|-----------------|-----------------|-----------------|---------------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| EFI-B DOM EXP | G847 | 201710      |                 | 11500373        | 11500438        | POWER SUPPLY CODE:AC125V:15A:NA | 1        | 1        | O/O | N    | 3    | 24    |     |         |     |      | V1701738   |            |

| Model          | Code | PCIL<br>Number | PCIL<br>Correction | Old part number | New part<br>number | Description                  | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|----------------|------|----------------|--------------------|-----------------|--------------------|------------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| EFI-B(DOM/EXP) | G847 | 201902         |                    | D6503057        | D3BN4040           | SERVICE PARTS:FAN:CASE:ASS'Y | 1        | 1        | O/O | N    | 3    | 13    |     |         |     |      | V1701989   | 17100083   |