

Model: Model TH-C1 Fax Option		Date: 1-Aug-05	No.: MB750001
Modified Article: Unique parts for Chinese version		Prepared by: H.K.	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety    (      )		

In order to start production of the Chinese version machines (B750-21), the following unique parts have been registered as spare parts.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B6032071	Keytop:Cover:Right:CHN	1		3	13	
	B7508540	Operating Instructions – FAX 1 Chinese	1		3	16	
	B7508541	Operating Instructions – FAX 2 Chinese	1		3	16	

## Gotenba (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Ricoh Savin Gestetner Lanier Fax Option Type 3232	120/60	USA	B750-17	
Ricoh Fax Option Type 3232	110/60	Taiwan	B750-19	
Ricoh Fax Option Type 3232	220,230,240/50, 60	China	B750-21	
Ricoh NRG Lanier Infotec Fax Option Type 3232	220,230,240/50, 60	Europe, etc	B750-27	
Ricoh NRG Fax Option Type 3232	220,230,240/50, 60	Asia, etc	B750-29	

Model: Model TH-C1 Fax Option		Date:31-Jul-06	No.: MB750002
Modified Article: Modular Harness		Prepared by: H.K.	
From: Technical Service Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (RoHS)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7505372	B7505231	HARNESS: MODULAR: NA & TWN	1	X/O	3	7	
B7505374	B7505232	HARNESS: MODULAR: EU&AA	1	X/O	3	7	

**Change:** The materials for these parts were changed.

**Reason:** To comply with the RoHS Directive.

**Note:** The functions of these parts were not changed.

#### IMPORTANT:

- The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N:

**Non-RoHS** compliant parts

Parts with the **new** P/N:

**RoHS** compliant parts

	RoHS Compliant Parts	Non-RoHS Compliant Parts
<b>RoHS</b> Compliant Machines	OK	<b><u>DO NOT USE</u></b>
<b>Non-RoHS</b> Compliant Machines	OK	OK

- Continue using** non-RoHS compliant parts on non-RoHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- DO NOT use** non-RoHS compliant parts on RoHS compliant machines.

**Note:** This is to make sure that all machines are in full compliance with the RoHS Directive.

Model: Model TH-C1 Fax Option

Date:31-Jul-06

No.: MB750002

**Gotenba (Japan) Production**

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Ricoh Savin Gestetner Lanier Fax Option Type 3232	120/60	USA	B750-17	K73603xxxxx
Ricoh Fax Option Type 3232	110/60	Taiwan	B750-19	K73603xxxxx
Ricoh Fax Option Type 3232	220,230,240/50, 60	China	B750-21	K73603xxxxx
Ricoh NRG Lanier Infotec Fax Option Type 3232	220,230,240/50, 60	Europe, etc	B750-27	K73603xxxxx
Ricoh NRG Fax Option Type 3232	220,230,240/50, 60	Asia, etc	B750-29	K73603xxxxx

Model: Model TH-C1 Fax Option		Date: 30-May-07	No.: MB750003
Modified Article: FCU		Prepared by: H.K	
From: Technical Service Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (RoHS)

**P/N Correction for Taiwan**

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7125172	B7125178	PCB: GWFCU3: TWN	1-1	X/O	3	3	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7125172	B7665132	PCB: GWFCU3: NA	1-1	X/O	3	3	
B7125174	B7665134	PCB: GWFCU3: EU	1-1	X/O	3	3	
B7125178	B7665136	PCB: GWFCU3: TWN	1-1	X/O	3	3	

**Change:** The materials for the part was changed.

**Reason:** To comply with the RoHS Directive.

**Note:** The functions of the part was not changed.

**IMPORTANT:**

- The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N:                      **Non-RoHS** compliant parts  
 Parts with the **new** P/N:                      **RoHS** compliant parts

	<b>RoHS</b> Compliant Parts	<b>Non-RoHS</b> Compliant Parts
<b>RoHS</b> Compliant Machines	OK	<b><u>DO NOT USE</u></b>
<b>Non-RoHS</b> Compliant Machines	OK	OK

- Continue using** non-RoHS compliant parts on non-RoHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- DO NOT use** non-RoHS compliant parts on RoHS compliant machines.

Model: Model TH-C1 Fax Option

Date: 30-May-07

No.: MB750003

**Note:** This is to make sure that all machines are in full compliance with the RoHS Directive.

**Gotenba (Japan) Production**

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Ricoh Savin Gestetner Lanier Fax Option Type 3232	120/60	USA	B750-17	K7351201006
Ricoh Fax Option Type 3232	110/60	Taiwan	B750-19	K7360100001
Ricoh Fax Option Type 3232	220,230,240/50, 60	China	B750-21	K7360201781
Ricoh NRG Lanier Infotec Fax Option Type 3232	220,230,240/50, 60	Europe, etc	B750-27	K7360100031
Ricoh NRG Fax Option Type 3232	220,230,240/50, 60	Asia, etc	B750-29	K7360100936