Technical Bulletin

PAGE: 1/1

Model: OR-C1 F	ax Option Type 3352		Dat	e: 02-Dec	-11	No.: RD596001	
Subject: Service Manual Correction					epared by: T. Nihei		
From: 2nd Tech S	Service Sect., MFP/P Tech Se	rvice Dept.					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	☐ Action	required	
	☐ Mechanical	☐ Electrication	al		⊠ Servic	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2		

Service Manual Correction

The areas in **bold** were corrected.

D596 Service Manual

"1. Installation - Fax Unit (D596)"

24. Do SP3-102 in the fax SP mode and enter the serial number for the fax unit.

Technical Bulletin

PAGE: 1/1

Model:OR-C1 Fax Option Type 3352 Da			Dat	e: 27-Jan-	12	No.: RD596002		
Subject: Service Manual Correction (RCN only -Certification decal)					Prepared by: T. Nihei			
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.								
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required		
		☐ Electric	al		⊠ Service	e manual revision		
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	it information		
	☐ Product Safety	Other ()	☐ Tier 2			

Service Manual Revision

Add the following description.

1. Installation

- G3 Interface Unit (D596 -11/-12)

No. 9

If a serial number decal is not attached to the fax unit, attach it to the unit's faceplate.

Attach the decal packaged with the G3 Interface Unit to the area shown in red below. This decal shows that the fax is compliant with Chinese communication standards.



Technical Bulletin

PAGE: 1/1

Model: OR-C1 Fax Option Type 3352 Date			Dat	te: 11-Apr-12		No.: RD596003		
Subject: Parts Catalog Correction (FCU Board)					ared by: T. Nihei			
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.								
Classification:	Classification: Troubleshooting		ormation		Action	required		
	☐ Mechanical	☐ Electric	al		Service	ce manual revision		
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information		
	☐ Product Safety	\square Other ()	☐ Tier 2			

Part number	Description	Q'ty	Int	Page	Index	Note
D5965194	PCB:FCU:EU:SERVICE PARTS:ASS'Y (EU/AA/CHN)	1	-	3	1	
D5965196	PCB:FAX CONTROL UNIT:TWN:SERVICE PARTS:ASS'Y	1	-	3	1	

Change:

- 1) The description of the FCU for the EU, Asia Pacific, and China markets was changed (the part highlighted in **bold** was added).
- 2) The FCU for the Taiwan market was added.

Reason:

- 1) To clarify that the same FCU is used for the EU, Asia Pacific, and China markets.
- 2) The FCU for the Taiwan market was missing from the Parts Catalog.

1 4			
	 •	_	

Technical Bulletin

PAGE: 1/3

Model:OR-C1 Fa	ax Option Type 3352		Dat	e: 04-Oct-	12	No.: RD596004		
Subject: G3 Decal Deletion					Prepared by: T. Nihei			
From: 2nd Tech S	Service Sect., MFP/P Tech Ser	vice Dept.						
Classification:	assification: Troubleshooting Part inform		ormat	tion	required			
	☐ Mechanical	☐ Electrica	al		⊠ Servic	e manual revision		
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information		
	☐ Product Safety	Other ()	☐ Tier 2			

Note: These corrections were made because the G3 decal was deleted in September 2011.

Service Manual Correction

D596 Service Manual


- 1. Installation
 - Fax Unit (D596)
 - Accessory

No.	Description	Q'ty
1.	Telephone Cable (NA only)	1
2.	Serial Number Label	1
3.	FCC Label (NA only)	1
4	C3 Decel	1
4.	O3 Decui	'
5.	Fax Keytops	2
6.	Copy Keytops	2
7.	Ferrite Core	1
8.	Fax Unit	1

Model:OR-C1 Fax Option Type 3352


Date: 04-Oct-12

No.: RD596004



1. Installation

- Fax Unit (D596)
 - Fax Installation



19. Attach the G3 decal to the front of the machine.

Technical Bulletin

Date: 04-Oct-12 No.: RD596004

PAGE: 3/3

Parts Catalog Correction

Model:OR-C1 Fax Option Type 3352

Fax Option Type 3352 (D596-01/02/03)

Deleted Part Number	Description	Page	Index	Note
D1206870	DECAL:SG3	3	6	

1.Fax Option (D596-01/02/03)

