



## Part Change Information List

Date: June 30, 2009

| Model            | Code | PCIL Nr. | PCIL<br>Correction | Old part<br>number | New part<br>number | Description         | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|------------------|------|----------|--------------------|--------------------|--------------------|---------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| AP-C2 FAX OPTION | D393 | 200906   |                    | D3935731           | D3935743           | PCB:GWFCU-IF2:ASS'Y | 1        | 1        | X/O |      | 3    | 22    |     |         |     |      | V0804884 | 8120250 |



Part Change Information List

Date: March 31, 2011

| Model            | Code | PCIL Nr. | PCIL<br>Correcti<br>on | Old part<br>number | New part<br>number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr.  |
|------------------|------|----------|------------------------|--------------------|--------------------|-------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|----------|
| AP-C2 FAX OPTION | D393 | 201103   |                        | D3930581           | D3930586           | BRACKET:FCU | 1        | 1        | X/O |      | 3    | 17    |     |         |     |      | V1100303 | 10120837 |