## RIGOH

## Modification Bulletin

Reissued: 20-May-05

Model: Model U-C1 Interchange Unit Type 1232

Date: 22-Mar-05

No.: MB481001a

#### **MB** Correction

The items in bold italics have been corrected or added.

Modified Article: P	arts catalog correction	Prepared by: S. Tomoe			
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	Parts catalog correction	U Vendor cha	ange	To meet standards	
Modification:	To facilitate assembly	To improve reliability		( )	
	Part standardization Other				

Incorrect	Description	Page	Incorrect	Correct	Note
part number			Index	Index	
AA080156	Bushing – M4	3	5	6	
52054527	Spring - Exit	3	6	5	

Change/Reason: The *index* for these parts were corrected.

# RIGOH

### Modification Bulletin

Model: Model U-C1 Interchange Unit Type 1232 Date			e: 29-Mar-0	5	No.: MB481002		
Modified Article: Decal				Prepared by: S. Tomoe			
From: 1st Tech. Support Sec. Service Support Dept.				1			
Reason for	Reason for Parts catalog correction Vendor			ange	neet standards		
Modification:		improve reliability		(	)		
	Part standardization	⊠ Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AA003021	AA003023	Decal – Exit Grip	1-1	X/O	3	20	

**Change:** The illustration on the decal was changed. **Reason:** To make it easier for the operator to clear a paper jam.

#### **RCL (Japan) Production**

Model	V/Hz	Destination	Code	Serial Number
Interchange unit	120/60	All RICOH subsidiaries,	B481-17	J3740800001
type 1232	220-240/50, 60	NRG, SAVIN, infotec		

RIGOH

### Modification Bulletin

Reissued: 12-Apr-05		
Model: Model U-C1 Interchange Unit Type 1232	Date: 29-Mar-05	No.: MB481003a
MB Correction		
The items in hold italics have been corrected or ad-	ded	

Modified Article: Solenoids			Prepared by: S. Tomoe				
From: 1st Tech. Sup	h. Support Sec. Service Support Dept.						
Reason for	Parts catalog correction	Vendor change		To meet standards			
Modification:	Modification To facilitate assembly To improv		e reliability	( )			
	Part standardization	Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AA145816	AA143653	Tension Roller Shaft	1-1	0/0	3	4	
B3004574	G3054574	Shaft Guide Plate	1-1	0/0	3	14	
B3004514	B4814514	DC Solenoid – Gate Pawl Lower	1-1	0/0	5	2	
B4815439	B4815493	Gate Unit Harness	1-1	0/0	5	9	
B3004503	B4814503	DC Solenoid – Gate Pawl Upper	1-1	0/0	5	10	

**Change:** The materials for these parts were changed to more environmentally-friendly types.

**Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.