ገጦጠ			
	닚		

Modification Bulletin

Model: Bellini Date		Date : 19-Oct-00		No.: MA294051		
Modified Article: I/F Board Fuse			Prepared by: J. Mochizuki			
From: Technical S	Services Dept., GTS Division		1			
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To r	neet standards	
Modification:	☐ To facilitate assembly ☐ To improve		ove reliability ()	
	☐ Part standardization	☐ Other				

The fuse (FU101) on the optional interface board has been registered as a service part. Please add the following item to the Interface Board Type 850 (B327) parts catalog.

Incorrect	Correct	Description	Q'ty	Int	Page	Index	Note
part number	part number						
	11070719	Fuse – K19371/1A	1		3	*3	

*: New Index

