

LCT Connection Unit Type A (G845)

LCT Connection Unit Type A (G845)


PARTS CATALOG

This catalog gives the numbers and names of parts on this machine.

1.Connector Unit (G845)	2
Parts Index	5

June ,30 ' 2006

1.Connector Unit (G845)



1.Connector Unit (G845)

Index No.	Part No.	Description	Q'ty Per Assembly
1	G004 3519	Stepping Screw	1
2	G845 1035	Compression Spring:Upper	2
3	G845 1033	Bracket:Sensor:Guide Plate	1
4	AW01 0107	Paper Feed Sensor	1
5	G845 1030	Bracket:Guide Plate:Upper	1
6	G845 5350	Harness:LCT	1
7	G845 1032	Bracket:Guide Plate:Lower	1
8	G845 1041	Bracket:Stay:Left	1
9	G845 1042	Bracket:Stay:Right	1
10	G845 1027	Bracket:Ground Plate	1
11	G845 1029	Hexagonal Nut:M12:T=7	1
12	G845 1028	Caster:40kgf	1

Index No.	Part No.	Description	Q'ty Per Assembly
101	0354 0080N	Screw:M4X8	
102	1105 0522	Edge Saddle - Les0510	
103	0353 0080N	Screw:M3X8	

Parts Index

Parts Index

Part No.	Description	Page and Index No.
G845 1027	Bracket:Ground Plate	3 - 10
G845 1028	Caster:40kgf	3 - 12
G845 1029	Hexagonal Nut:M12:T=7	3 - 11
G845 1030	Bracket:Guide Plate:Upper	3 - 5
G845 1032	Bracket:Guide Plate:Lower	3 - 7
G845 1033	Bracket:Sensor:Guide Plate	3 - 3
G845 1035	Compression Spring:Upper	3 - 2
G845 1041	Bracket:Stay:Left	3 - 8
G845 1042	Bracket:Stay:Right	3 - 9
G845 5350	Harness:LCT	3 - 6

Part No.	Description	Page and Index No.
G004 3519	Stepping Screw	3 - 1

Part No.	Description	Page and Index No.
AW01 0107	Paper Feed Sensor	3 - 4

Part No.	Description	Page and Index No.
0353 0080N	Screw:M3X8	3 - 103
0354 0080N	Screw:M4X8	3 - 101
1105 0522	Edge Saddle - Les0510	3 - 102