K] ¦
	II ՄԽI Մ	Иπ
	ιτολίο	ΊШЦ

Technical Bulletin

_	_	_	_	_	_
D	Λ	G	⊏.	1	11
г	м	J	┗.		,

Model: Model S-	F2		Dat	e: 30-Jan-03	No.: RH556001
Subject: Service Manual Correction (Model S-F2)			Prepared by: M. Mano		
From: Technical Service Sec. Service Planning Dept.					
Classification:	Troubleshooting	☐ Part information ☐ Action re		n required	
		☐ Electric	al	☐ Servi	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive 🗌 Retro	fit information

Please apply the following corrections to your Service Manuals.

NIC FAX Service Manual:

Page 3-24, Sec. 3.6.1 START ADDRESS

Incorrect

Firmware	Start address	Firmware file type	
NICF	200000H	*. rdt / *. mdt	
JPEG	20000011	. racr . mac	

Correct:

Firmware	Start address	Firmware file type
NICF	200000H	*. rdt / *. mdt
JPEG	2000011	*.bin