


Model: PALM-B (D567, PB1030)		Date: 15-Jun-11	No.: RD567001
Subject: Plate: Heat Sink: 1		Prepared by: M. Ishihara	
From: 2 nd Overseas Tech Support Sec. 2 nd PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
-	D5672744	Plate: Heat Sink: 1	0-1	-	3	14	New Index
-	D5672745	Plate: Heat Sink: 2	0-1	-	3	15	New Index

Reason / Change: To prevent temperature increasing when the optional heater is installed, 2 plates were newly added as shown below.



D5672744 (Plate: Heat Sink: 1)



D5672745 (Plate: Heat Sink: 2)