

Model: LE-C1 Paper Feed Unit PB1090		Date: 6-Feb-20	No.: RD794001
Subject: Service manual correction: Revised laser safety regulation		Prepared by: H.Saito	
From: 1st Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input checked="" type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

To meet revised laser safety regulation, please add the section below to your field service manual.

PB1090 Paper Feed Unit → 1. Replacement and Adjustment

Caution Decal Location

