



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Model AT-C1 LCIT (PB3010)	B801	200903		B8016123	B8006123	BRACKET:ARM:REMOVER/INSTALL:RIGHT	1	1	X/O		5	15					V0803830
Model AT-C1 LCIT (PB3010)	B801	200903			B8012313	GUIDE:PAPER FEED UNIT:LOWER	0	1			27	4			Y		V0003351



Part Change Information List

Date: May 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
AT-C1 LCIT (PB3010)	B801	200905		AB030787	AB030831	TIMING PULLEY:1ST:DRIVE	1	1	X/X		11	25	B		Y		V0804832
AT-C1 LCIT (PB3010)	B801	200905		B8012730	B8012733	SHAFT:SLIDER:DRIVE:PRESS FIT	1	1	X/X		11	20	B		Y		V0804832
AT-C1 LCIT (PB3010)	B801	200905		B8011059	B8001059	COVER:BURRING:BASE	1	1	X/O		15	10					V0803830



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	200906		B8012812	D3522816	GROUND PLATE:JOINT:DRIVE	1	1	X/O		11	27					V0901490	9050962



Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	200908		C4107632	D3511120	CASTER:DIA50H59:STOPPER:YES	2	2	X/O		5	7	A		Y		V0901758	9051154
AT-C1 LCIT (PB3010)	B801	200908		A5071096	A5071096A	PHILIPS SCREW - M5X6	8	8	X/O		5	9	A		Y		V0901758	9051154
AT-C1 LCIT (PB3010)	B801	200908		B8012711	D3522711	TANDEM LCT:LEFT:EXP:ASS'Y	1	1	X/O		11	1					V0901490	9050962



Part Change Information List

Date: September 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	200909		AH012036	D3511120	CASTER:DIA50H59:STOPPER:YES	2	2	X/X		5	8	A	X/O	RB801002a		V0901758	9051154



Part Change Information List

Date: January 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201001		G8322584	D3522586	HOOK:REAR:VERTICAL TRANSPORT	1	1	O/O		3	10					V0902323	9080654
AT-C1 LCIT (PB3010)	B801	201001		D3511120	D3511119	CASTER:DIA50H59:STOPPER:YES	2	2	O/O		5	8					V0903075	9110988
AT-C1 LCIT (PB3010)	B801	201001		AA082101	GA082010	BUSHING:DIA6:DIA10:9	1	1	X/O		31	18					V0903189	9111023



Part Change Information List

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201002		G8322583	D3522585	HOOK:FRONT:VERTICAL TRANSPORT	1	1	O/O		3	9					V0902323	9080654



Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201003		B8012512	B8012517	PAPER FEED UNIT:ASS'Y	1	1	X/O		13	1					V0903189	9111023



Part Change Information List

Date: November 30, 2010

Model	Code	PCIL Nr.	PCIL Correctio	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201011		B8006115	D3516115	COVER:ARM:FRONT:DOM	2	2	O/O		3	17					V1002568	10100702
AT-C1 LCIT (PB3010)	B801	201011		B8006117	D3516117	COVER:ARM:REAR:DOM	2	2	O/O		3	19					V1002568	10100702



Part Change Information List

Date: December 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201012		B2232778	D0892778	BRACKET:SENSOR:FEED	1	1	X/O		13	4					V1002614	10101257



Part Change Information List

Date: March 31, 2011

Model	Code	PCIL Nr.	PCIL Correcti on	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201103			B8012722	TANDEM TRAY:LEFT	0	1			10	40			RB801004		V1100379	



Part Change Information List

Date: May 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		13	6					V1002614	10101257



Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 LCIT (PB3010)	B801	201110		B8006116	D3516116	COVER:ARM:RIGHT:DOM	2	2	O/O		3	18					V1002568	10100702



Part Change Information List

Date: June 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AT-C1 LCIT (PB3010)	B801	201406		B8015311	D7475311	HARNESS:CEBU:TANDEM TRAY:ASS'Y	1	1	O/O		11	32					V1300315	13011484



Part Change Information List

Date: Feburary 1, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AT-C1 LCIT_PB3010_	B801	201601		AA043599	AA043714	TIMING BELT:60S3M588	1	1	O/O	N	11	13					V1502639	15090525



Part Change Information List

Date: Apeil 4, 2017

[illegible]