RICOH

Modification Bulletin

PAGE: 1/1

Reissued: 27-Jun-07

Model: Model U-C1 Platen Cover (Type 120)	Date: 22-Mar-05	No.: MB484001a

MB Reissue

The items in *bold italics* were corrected or added.

Modified Article: Hinge			Prepared by: H.K.				
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	Parts catalog correction	Vendor changeTo improve reliability		To meet standards			
Modification:	To facilitate assembly			()			
	Part standardization	🛛 Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G3291320	G3291361	Platen Cover Sheet	1-1	O/O	3	1	
G3291330	G3291358	Cushion – Platen Cover	6-6	O/O	3	2	
A1931248	G3291355	Platen Cover Hinge Assembly	1-1	O/O	3	7	
B4061383	B4841383	Bracket - Platen Cover	1-1	0/0	3	10	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

RICOH

Modification Bulletin

PAGE: 1/1

Model: Model U-C1 / TH-C1Platen Cover (Type 120)				ate: 09-Sep	o-07	No.: MB484002		
Modified Article: Platen Cover Sheet				Prepared by: H.K.				
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	Parts catalog correction	U Vendor	cha	ange	Other			
Modification:	To facilitate assembly	🗌 To improv		e reliability	To meet standards			
	Part standardization	Product Safety		afety	()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3291361	G3291371	Platen Cover Sheet	1-1	X/O	3	1	

For details, please refer to RTB RB051038 / RTB RB156038.