

Model: A-C2/B-C2 Punch Kit		Date: 26-Jul-06	No.: MB377001
Modified Article: Punch Unit		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> To meet standards (RoHS compliant) <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3776012	B3776014	Punch Unit Assembly 2/4Holes	1-1	X/O	3	2	1

Change: The materials for these parts were changed.

Reason: To comply with the RoHS Directive.

Note: The functions of these parts were not changed.

IMPORTANT:

- The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts
 Parts with the **new** P/N: **RoHS** compliant parts

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	OK	<u>DO NOT USE</u>
Non-RoHS Compliant Machines	OK	OK

- **Continue using** non-RoHS compliant parts on non-RoHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.

- **DO NOT use** non-RoHS compliant parts on RoHS compliant machines.

Note: This is to make sure that all machines are in full compliance with the RoHS Directive.

Model: Adonis-C2/Bellini-C2 Punch Kit Type 1045		Date: 30-Mar-07	No.: MB377002
Modified Article: Punch Kit Type 1045		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3527506	B5457506	Screw	4-4	O/O	3	1	
AX060258	AX060307	Brushless Motor	1-1	O/O	3	3	
B3777017	B3777111	Punch Unit – 2-3 Hole	1-1	O/O	3	5	
B3777027	B3777112	Punch Unit – 2-4 Hole	1-1	O/O	3	5	
B3777031	B3777113	Punch Unit – 4 Hole	1-1	O/O	3	5	
AX210077	AX210096	Magnetic Spring Clutch 42Z	1-1	O/O	3	9	
A8127411	B5457411	Spacer – 2mm	1-1	O/O	3	10	
A8127412	B5457412	Spacer – 1mm	2-2	O/O	3	10	
AW010070	AW010123	Photosensor – PS- R11D1-B	1-1	O/O	3	14	
A6971125	AA143790	Stepped Screw – Lever	1-1	O/O	3	15	
B3775331	B3775366	Relay Harness – Punch Unit 2/3 Holes (-17)	1-1	O/O	3	25	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model: Adonis-C2 Punch Kit type 1045		Date: 30-Mar-07	No.: MB377003
Modified Article: Brushless Motor		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX060210	AX060258	Brushless motor	1-1	X/O	3	3	

Change/Reason: Parts standardization.

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Punch Kit Type 1045	-	USA	B377-17	1710957 -
Punch Kit Type 1045	-	Europe, Asia	B377-27	2705215 -
Punch Kit Type 1045	-	Northern Europe	B377-31	3101400 -