

Model:Triton-C1 Punch Unit(Hole Punch Unit Type 3131)		Date: 2-Aug-05	No.: MB734001
Modified Article: Bracket / Stay		Prepared by: M. Tsuyuki	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change/Reason: The Parts Catalog was corrected as follows.


Old part number	New part number	Description	Q'ty	Int	Page	Index
B7341116	B7341516	Catch Magnet (4407837720) Bracket (44210658000)	1	X/O	5	19
B7341134	B7341534	Bracket (44210016000) Bracket (6LE68046000)	1	X/O	5	28
B7341124	B7341524	Bracket (44210658000) Stay (6LE67300000)	1	X/O	5	30
B7341132	B7341532	Frame (44210658000) Frame (6LE68046000)	1	X/O	5	38

Model: Triton-C1 Punch Unit (Hole Punch Unit Type 3131)		Date: 10-Aug-05	No.: MB734002
Modified Article: Bracket / Stay		Prepared by: M. Tsuyuki	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change/Reason: The Parts Catalog was corrected as follows.

Old part number	New part number	Description	Q'ty	Int	Page	Index
B7341116	B7341516	Catch Magnet (4407837720) Bracket (44210658000)	1	X/O	5	19
B7341134	B7341534	Bracket (44210016000) Bracket (6LE68046000)	1	X/O	5	28
B7341124	B7341524	Bracket (44210658000) Stay (6LE67300000)	1	X/O	5	30
B7341132	B7341532	Frame (44210658000) Frame (6LE68046000)	1	X/O	5	38

2. PUNCH MAIN BODY





Part Change Information List

Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
TR-C1 Punch Unit (Hole Punch Unit Type 3131)	B734	201004		B7237039	B7239739	SCREW-M4X6 (X0-02572000)	11	11	O/O		5	43					V0903228	