

Model: Mojito-C1/C2		Date: 13-Mar-03	No.: RA293029
Subject: PostScript3 (B339) Firmware Histries		Prepared by: F.Noguchi	
From: Technical Services Sec. Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Other (Information)		

This is to inform of the modification history for the PostScript3 Kit Type 700 firmware of the Printer Controller Type 700/1055 (B337/B590).

Note that there are two types of firmware, both of which have been designed for specific brands as shown below:

Destination	Part Number	Product Codes/Brands
Generic	B339 5800	B339-01
		Ricoh, Savin, Gestetner, Nashuatec, Rexrotary, Infotec
Lanier	B339 5814	B339-14
		Lanier

Note: The Printer Controller Type 1055 (B590) for the Mojito-C2 requires version 1.35 or newer.

< Firmware Version and Part Number Suffix for Each Destination >

Destination	Generic	Lanier	Cut-in
Part Number	B339 5800	B339 5814	Serial Number
Version	Suffix	Suffix	
1.33	A	A	From 1st production
1.35	B	B	Form Aug/'02 production

< Version 1.33 >

Destination	Generic	Lanier
Part Number	B337 5800	B337 5814
Check SUM	3E20	3E20

Note: This is information only, as version 1.33 was used from the first lot of mass production.

< Version 1.35 >

Destination	Generic	Lanier
Part Number	B337 5800 A	B337 5814 A
Check SUM	209B	209B

1. Supports the Mojito-C2

The machine code for the Mojito-C2 has been added.