

Model: K-C1 Paper Tray Unit/2-tray (PS450)		Date: 21-Oct-09	No.: RB384001
Subject: Caster Part Change		Prepared by: M. Saiki	
From: 2nd Tech Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other () <input type="checkbox"/> Tier 2		

Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
AH012037	D3511121	Caster	4-4	X/X	3	16	X/O as a Set
B8001103	A5071096	Philips Screw – M5x6	8-8	X/X	3	17	

Change: The thickness of the caster holder is thicker than the old one.

Reason: Vendor change

Note: Those parts are interchangeable as a set.

