

| | | | |
|---|--|-----------------------|---------------|
| Model: R-C2 Paper Feed Unit PS490 | | Date: 8-Sep-09 | No.: RB390001 |
| Subject: Caster | | Prepared by: S. Tomoe | |
| From: 2nd Tech Support Sec. Service Support Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other () <input type="checkbox"/> Tier 2 | | |


| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------------------|------|-----|------|-------|------|
| A5071096 | | Pan Head Screw M5x5 | 16-8 | | 3 | 17 | A |
| AH012036 | D3511120 | Caster: Dia50H59: Stopper: Yes | 4-2 | O/O | 3 | 16 | A, B |
| | D3511121 | Caster: Dia50H59: Stopper: No | 0-2 | | 3 | 41 | A |

Note A

Change/Reason: Parts Catalog Correction

Note B

Change/Reason: Parts standardization.



| | | | |
|--|--|---------------------------|---------------|
| Model: R-C2 Paper Feed Unit PS490 | | Date: 21-Oct-09 | No.: RB390002 |
| Subject: Motor Bracket | | Prepared by: Tomoko Nihei | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-----------------------|------|-----|------|-------|------------|
| B3842720 | B3842784 | Bracket: DC Motor:1 | 1-1 | X/O | 9 | 15 | Set as O/O |
| A2672847 | | Bushing – Motor Shaft | 2-0 | | 9 | 4 | |

Change: The shape of the bracket was changed, eliminating the need for the bushing.
Reason: To facilitate assembly/replacement in the field.

