ISSUED ON: November 15, '96

Model	1-bin Sorter	Volt/Hz	Date of Modification	Serial Number		
Modified Article		No serial number cut-in information				
Reason for Modification	Parts catalog correction					

The following should be corrected. Please correct your part catalog.

1. The following parts have been modified.

Old Part Number	New Part Number	Description	Q'ty	Index No.	Page
AF022090	AF022098	Driven Roller	1	4	3
A0493371	G0121531	Magnet	2	35	3

for

S. Fujii, General Manager

2nd. Field Information Dept. QAC

RICOH

Modification Bulletin

PAGE: 1/1

Model: PT200 Da			Date	e: 19-Mar-97	No: 2	
Modified Article: Bushing-6mm			Prepared by: K.Ugaeri			
From: QAC 2nd Field Information Dept.		Checked by: S. Fujii				
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To		ange 🔲 To r	neet standards	
Modification:	☐ To facilitate assembly	oxtimes To improve reliability ()		
	☐ Part Standardization	☐ Other				

To reduce the noise from the 6mm Bushing, the material has been changed from January Production '97.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
AA080220		Bushing-6mm	2-2	x/o	2	3	