RICOH


Technical Bulletin

PAGE: 1/1

| Model: R – C5 One-bin Tray | | | Date: 14-Jun-10 | | 10 | No.: RD367001 | | |
|---|------------------|--------------------|-----------------|-----------------------|------------------------|--------------------|--|--|
| Subject: Guide Plate | | | | Prepared by: T. Nihei | | | | |
| From: 1st Overseas Tech Support Sec., 1st PQM Dept. | | | | | | | | |
| Classification: | | ☐ Part information | | tion | Action | required | | |
| | ☐ Mechanical | ☐ Electrical | | ☐ Servi | | ce manual revision | | |
| | ☐ Paper path | ☐ Transmit/rec | | eive | ☐ Retrofit information | | | |
| | ☐ Product Safety | Other (| |) | | | | |

| Old part | New part | Description | Q'ty | Int | Page | Index | Note |
|----------|----------|--------------------|------|-----|------|-------|------|
| number | number | | | | | | |
| D3674164 | D3674165 | GUIDE PLATE - GATE | 1-1 | X/O | 3 | 21 | |

Change: The shape of the guide plate was changed. **Reason:** To ensure that the separation guide plate does not interfere with the movement of the fusing pressure release lever.



Cut-in S/N:

| Model code | Serial No. |
|------------|--------------|
| D367-17 | M6801401601~ |