



Part Change Information List

Date: August 30, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201308			D5191415	GUIDE MILER:UNIFORM:TRAILING EDGE:MB80015:ASS'Y	0	1			18	10			Y		V1301891	12122343



Part Change Information List

Date: September 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201407		D5191415	D7371415	GUIDE MILER:UNIFORM:TRAILING EDGE:MB80015:ASS'Y	1	1	X/O		19	10					V1400836	14030889

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201501			D7373166	PIN:1706:FF51706	0	2			55	34			Y		V1404119	14120171
Ring Binder RB5010	D519	201501			D7373165	PLAIN WASHER:4.3X9X0.8CF:EE39829	0	4			55	34			Y		V1404119	14120171



Part Change Information List

Date: June 4, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201505		D3921305	D7371305	GUIDE PLATE:TRANSPORT:B:MB70082	1	1	X/O	N	7	3					V1500043	14120399
Ring Binder RB5010	D519	201505		D3921304	D7371304	GUIDE PLATE:TRANSPORT:A:MB70081	1	1	X/O	N	7	12					V1500043	14120399
Ring Binder RB5010	D519	201505		D3921240	D7371240	GUIDE PLATE:TRANSPORT:C:MB10729	1	1	X/O	N	7	13					V1500043	14120399
Ring Binder RB5010	D519	201505		D3921306	D7371306	GUIDE PLATE:TRANSPORT:C:MB70083	1	1	X/O	N	9	1					V1500043	14120399
Ring Binder RB5010	D519	201505		D3921307	D7371307	GUIDE PLATE:TRANSPORT:D:MB70085	1	1	X/O	N	9	3					V1500043	14120399
Ring Binder RB5010	D519	201505		D3921242	D7371242	GUIDE PLATE:TRANSPORT:C:MB10731	1	1	X/O	N	9	21					V1500043	14120399



Part Change Information List

Date: August 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201507		D3921241	D7371241	GUIDE PLATE:TRANSPORT:C:MB70093	1	1	X/O	N	7	6					V1500043	14120399



Part Change Information List

Date: September 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201508		D3921241	D7371241	GUIDE PLATE:TRANSPORT:C:MB70093	1	1	X/O	N	7	6					V1500043	14120399



Part Change Information List

Date: October 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201509		D3927711	D7377711	LABEL:CARTRIDGE:MB10001	1	1	X/O	N	3	11					V1501620	15040640

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5010	D519	201901		D3921289	D7371289	DC STEPPER MOTOR:MB70022	1	1	X/O	N	51	21					V1801911	
Ring Binder RB5010	D519	201901		D3921310	D7371310	DC STEPPER MOTOR:MB70118	5	5	X/O	N	51	25					V1801911	
Ring Binder RB5010	D519	201902		D3921112	D7371112	CLAMP:UNI:MB92004:ASS'Y	1	1	X/O	N	18	5					V1303776	13110470