



Part Change Information List

Date: July 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201407			D7371415	GUIDE MILER:UNIFORM:TRAILING EDGE:MB80015:ASS'Y	0	1			19	10			Y		V1400836	14030889

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201501			D7373165	PLAIN WASHER:4.3X9X0.8CF:EE39829	0	4			55	34			Y		V1404119	14120171
Ring Binder RB5020	D737	201501			D7373166	PIN:1706:FF51706	0	2			55	35			Y		V1404119	14120171



Part Change Information List

Date: June 4, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201505		D3921305	D7371305	GUIDE PLATE:TRANSPORT:B:MB70082	1	1	X/O	N	7	3			Y		V1500043	14120399
Ring Binder RB5020	D737	201505		D3921304	D7371304	GUIDE PLATE:TRANSPORT:A:MB70081	1	1	X/O	N	7	12			Y		V1500043	14120399
Ring Binder RB5020	D737	201505		D3921240	D7371240	GUIDE PLATE:TRANSPORT:C:MB10729	1	1	X/O	N	7	13			Y		V1500043	14120399
Ring Binder RB5020	D737	201505		D3921306	D7371306	GUIDE PLATE:TRANSPORT:C:MB70083	1	1	X/O	N	9	1			Y		V1500043	14120399
Ring Binder RB5020	D737	201505		D3921307	D7371307	GUIDE PLATE:TRANSPORT:D:MB70085	1	1	X/O	N	9	3			Y		V1500043	14120399
Ring Binder RB5020	D737	201505		D3921242	D7371242	GUIDE PLATE:TRANSPORT:C:MB10731	1	1	X/O	N	9	21			Y		V1500043	14120399



Part Change Information List

Date: August 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201507		D3921241	D7371241	GUIDE PLATE:TRANSPORT:C:MB70093	1	1	X/O	N	7	6					V1500043	14120399



Part Change Information List

Date: October 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201509		D3927711	D7377711	LABEL:CARTRIDGE:MB10001	1	1	X/O	N	3	11			Y		V1501620	15040640



Part Change Information List

Date: May 12, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201704		D7375600	D7375601	PCB:MAIN:MB70292:ASS'Y	1	1	X/O	N	55	14					V1303244	13090244
Ring Binder RB5020	D737	201704		D7375602	D7375603	PCB:MAIN:MB70292:ASS'Y	1	1	X/O	N	55	14					V1404117	14120092
Ring Binder RB5020	D737	201704		D7375601	D7375602	PCB:MAIN:MB70292:ASS'Y	1	1	X/O	N	55	14					V1304291	13121165

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5020	D737	201811		D3921310	D7371310	DC STEPPER MOTOR:MB70118	5	5	X/O	N	27	1					V1801865	18081317
Ring Binder RB5020	D737	201901		D3921289	D7371289	DC STEPPER MOTOR:MB70022	1	1	O/O	N	51	21				only for 17	V1801865	18081317
Ring Binder RB5020	D737	201901		D3921289	D7371289	DC STEPPER MOTOR:MB70022	1	1	X/O	N	51	21				only for 27	V1801865	18081317
Ring Binder RB5020	D737	201901		D7371120	D7371125	UNIFORM UNIT:MB92006:ASS'Y	1	1	O/O	N	21	1					V1801863	18050167
Ring Binder RB5020	D737	201902		D3921112	D7371112	CLAMP:UNI:MB92004:ASS'Y	1	1	X/O	N	21	5					V1303776	13110470