

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 27-Jun-02	No.: MB461001
Modified Article: Operating instructions		Prepared by: S. Tomoe	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

The Printer Reference Guide has been registered as a service part.

New part number	Description	Q'ty	Page	Index	Note
B4618607	Operating Instruction – Printer Reference 1	1	3	16	

Reissued: 11-Nov-03

Model: Russian-C2 Printer/Scanner Cont. Type 1027	Date: 30-Oct-03	No.: MB461002a
---	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Network Interface Board		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Other	

Due to a firmware version change, the Network Interface Board has been changed.

The P/N change below is a Parts Catalog correction, as G3355800 is the P/N for the Japan domestic model while G3355817 is for all other models (which has been used since the beginning of mass production). The separate P/N is due to a difference in firmware.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3355800	G3355817	Network Interface Board	1	X/O	2	9	

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 26-Apr-04	No.: MB461003
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The DIMM have been changed for use on the European model.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B453 5117	B453 5118	Printer/Scanner ROM DIMM	1	X/O	3	8	
B461 5117	B461 5118	Printer ROM DIMM	1	X/O	3	8	

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 26-Apr-04	No.: MB461004
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following have been changed in accordance with the release of Printer System firmware v2.04.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B453 5118	B505 5117	Printer ROM Dimm	1	X/O	3	8	
B461 5118	B506 5117	Printer ROM Dimm	1	X/O	3	8	

[Japan Production]

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Printer/Scanner Controller Type 1027	USA	B453-10	J07309xxxxx
	USA, Europe	B453-14	L121309xxxx
	USA	B453-15	J07309xxxxx
	USA, Asia	B453-17	J0730800001
	Europe	B453-22	J07309xxxxx
	Europe	B453-24	L121309xxxx
	Europe	B453-26	4N1093xxxx
	Europe, etc	B453-27	J07309xxxxx
Printer Controller Type 1027	USA	B461-10	J08310xxxxx
	USA, Europe	B461-14	L119310xxxx
	USA	B461-15	J08310xxxxx
	USA, Asia	B461-17	J08310xxxxx
	Europe	B461-22	J08310xxxxx
	Europe	B461-24	L119310xxxx
	Europe	B461-26	4M9103xxxx
	Europe, etc	B461-27	J08310xxxxx

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 10-May-06	No.: MB461005
Modified Article: HDD		Prepared by: Y.Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index
B0295760	B0955763	HD:TOSHIBA:MK4032GAX:ROHS	1-1	O/O	3	3

Change: The part number of the HDD unit was changed.

Reason: The old HDD was discontinued from production.

Note: Both parts have the same function and performance.

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 10-Sep-08	No.: MB461006
Modified Article: HDD		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index
B0955763		HD:TOSHIBA:MK4032GAX:ROHS	1-1	X/O	3	3
	B0955764	HD:FUJITSU:MHW2040AT:ROHS				

Change: The part number of the HDD unit was changed.

Reason: The old HDD was discontinued from production.

Important: When you install the new HDD for the first time, update the Controller firmware to the following version or newer:

Firmware Number: **B0315380G**

Version: **5.21.1**



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C2 Printer Controller Type 1027	B420	200906		B0955763	B0955764	HDD:FUJITSU:MHV2040AT:ROHS	1	1	O/O		3	3					V0803439	