

| | | | |
|--|--|------------------------|---------------|
| Model: Printer / Scanner Unit Type 2027 | | Date: 10-May-06 | No.: MB577001 |
| Modified Article: HDD | | Prepared by: Y. Ohtani | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index |
|-----------------|-----------------|---------------------------|------|-----|------|-------|
| B0955760 | B0955763 | HD:TOSHIBA:MK4032GAX:ROHS | 1-1 | O/O | 3 | 3 |

Change: The part number of the HDD unit was changed.

Reason: The old HDD was discontinued from production.

Note: Both parts have the same function and performance.



Part Change Information List

Date: July 31, 2009

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|---------------------------|------|----------|--------------------|--------------------|--------------------|----------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| R-C3 Printer/Scanner Unit | B577 | 200907 | | B0955763 | B0955764 | HDD:FUJITSU:MHW2040AT:ROHS | 1 | 1 | O/O | | 3 | 3 | | | | | V0803439 | |