RICOH

Modification Bulletin

PAGE: 1/2

Model: Russian-C4 Fax Unit Date			ate: 21-Aug-06		No.: MB766001	
Modified Article: FCU				Prepared by: S. Tomoe		
From: Technical Service Dept., GTS Division						
	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization		•	ange e reliability	⊠ To n (Ro	neet standards HS)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B7125172	B7665132	PCB: GWFCU3: NA	1-1	X/O	3	4	
B7125174	B7665134	PCB: GWFCU3: EU	1-1	X/O	3	4	
B7125178	B7665136	PCB: GWFCU3: TWN	1-1	X/O	3	4	

Change: The materials for the part was changed. **Reason:** To comply with the RoHS Directive.

Note: The functions of the parts were not changed.

IMPORTANT:

The materials for the parts were changed before the part numbers were changed.
 To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts Parts with the **new** P/N: **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	OK	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until
 the stock of these parts runs out. Then, start using RoHS compliant parts on the
 non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification Bulletin

PAGE: 2/2

Model: Russian-C4 Fax Unit Date: 21-Aug-06 No.: MB766001

Gotenba (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Fax Option Type 3030	120/60 220,230,240/50, 60	NA, LA	B766-17	K8860100001
	120/50	Taiwan	B766-19	K8860101231
	220,230,240/50, 60	China	B766-21	K8860101241
	220,230,240/50, 60	Europe, etc	B766-27	K8851203507
	220,230,240/50, 60	Asia,	B766-29	K8860102492

RICOH

Modification Bulletin

PAGE: 1/2

Model: Russian-C4 Fax Unit Date			ite: 21-Aug-06		No.: MB766002	
Modified Article: Modular Harness				Prepared by: S. Tomoe		
From: Technical Service Dept., GTS Division						
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization	☐ Vend☐ To in☐ Othe	nprove	ange e reliability	⊠ To n (Ro	neet standards HS)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B7665282	B7665236	Harness:Modular:Tel:NA	1-1	X/O	3	15	
B7665284	B7665237	Harness:Modular:Tel:EU	1-1	X/O	3	15	
B7665270	B7665230	Harness:Modular:Line	1-1	X/O	3	16	
B7665271	B7665232	Harness:Modular:Line:EU	1-1	X/O	3	16	

Change: The materials for the part was changed. **Reason:** To comply with the RoHS Directive.

Note: The functions of the parts were not changed.

IMPORTANT:

The materials for the parts were changed before the part numbers were changed.
 To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts Parts with the **new** P/N: **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	OK	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until
 the stock of these parts runs out. Then, start using RoHS compliant parts on the
 non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification Bulletin

PAGE: 2/2

Model: Russian-C4 Fax Unit Date: 21-Aug-06 No.: MB766002

Gotenba (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Fax Option Type 3030	120/60 220,230,240/50, 60	NA, LA	B766-17	K8860300001
	120/50	Taiwan	B766-19	K8860302331
	220,230,240/50, 60	China	B766-21	K8860402326
	220,230,240/50, 60	Europe, etc	B766-27	K8860302990
	220,230,240/50, 60	Asia,	B766-29	K8860403538