Modification Bulletin


PAGE: 1/1

Model: NAD 30S/30/40 LCT (RT36)			te: 30-Aug-0	0	No.: MA683001		
Modified Article: Side Plate				Prepared by: E. Fukuyama			
From: Technical Ser	vices Dept., GTS Division		7				
Reason for	☐ Parts catalog correction	☐ Vendor cl	nange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improv	e reliability	()		
	☐ Part standardization	Other					

The following have been registered as service parts.

New part number	Description		Int	Page	Index
A6832550	Side Plate : Front	0-1	-	7	28
A6832560	Side Plate : Rear	0-1	-	7	29

3.PAPER TRAY (A683)



	R	ጠ	ПΠ
KU	(H)	IJ	別

Modification:

Modification Bulletin

Model: NAD 30S/30/40 LCT (RT36)			e: 5-Jun-03		No.: MA683002	
Modified Article: Hinge Bracket				Prepared by: Y.Urushihara		
From: 1st Tech. Sup						
Reason for	☐ Parts catalog correction			☐ To m	eet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	

PAGE: 1/1

The following has been changed due to a vendor change.

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A6831280	B5431280	Hinge Bracket	1	0/0	3	18	

☐ Other



Modification **B**ulletin

PAGE: 1/1

Model: NAD 30S/30/40 LCT (RT36)	Date: 2-Jul-03	No.: MA683003a
---------------------------------	----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Frame – Large Capacity Tray			Prepared by: Y.Urushihara			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor change☐ To improve reliability☑ Other		☐ To meet standards		
Modification:	☐ To facilitate assembly			()		
	☐ Part standardization					

The following P/N has been added to the Parts Catalog, as it was previously missing.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B5431050	Frame – Large Capacity Tray	0-1		9	19	

