

Model: Adonis-C3 LCT (RT45)		Date: 15-Nov-05	No.: MB543001
Modified Article: Brushless Motor		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX060140	AX060317	Brushless Motor – DC24V 12.3W	1-1	O/O	11	7	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

[RCL (Japan) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NUMBER
RT45	USA	B543-17	J62510xxxxx
Infotec RT45	Europe	B543-26	J62510xxxxx
RT45	Europe, Asia	B543-27	J62510xxxxx

Model: Adonis-C3 LCT (RT45)		Date: 3-Jun-08	No.: MB543002
Modified Article: Brushless Motor		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX060317	AX060366	Brushless Motor – DC24V 12.3W	1-1	O/O	11	7	

Change/ Reason: Production was stopped on the older version.

[RCL (Japan) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NUMBER
RT45	USA	B543-17	J62510xxxxx
Infotec RT45	Europe	B543-26	J62510xxxxx
RT45	Europe, Asia	B543-27	J62510xxxxx

Model: Adonis-C3 LCT (RT45)		Date: 11-Mar-09	No.: MB543003
Modified Article: Brushless Motor		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

MB CANCELLATION

Change: MB543002 was cancelled.

Reason: A delay in the provision of the new parts from the vendor into SPC stock.

Cancelled part number	Current part number	Description	Q'ty	Int	Page	Index	Note
AX060366	AX060317	Brushless Motor – DC24V 12.3W			11	7	

[RCL (Japan) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NUMBER
RT45	USA	B543-17	J62510xxxxx
Infotec RT45	Europe	B543-26	J62510xxxxx
RT45	Europe, Asia	B543-27	J62510xxxxx