Modification Bulletin

Model: LCT for Moji	to-C2	e: 26-Feb-0	3	No.: MB587001				
Modified Article: F	eed Rollers		Prepared by: F.Noguchi					
From: Technical Ser	vices Sec. Service Planning D							
Reason for	Parts catalog correction	Vendor change			🗌 To m	neet standards		
Modification:	To facilitate assembly	🖾 To im	To improve reliability)		
	Part standardization							

The Paper Feed Rollers have been changed due to parts standardization and to increase their target yield from 300K to 1000K.

Note:

RIGOH

- 1) At PM parts replacement, be sure to check the target yield setting and change it in SP mode if necessary, depending on whether the part to be installed is old or new.
- 2) Color of the rollers: New type: Light blue Old type: Gray
- 3) Mainframes (Mojito-C2) containing ver0.15 at arrival have been fitted with the new PM parts.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AF0300050 -		Pick-up Roller	1 - 1	X/X	7	26	*
	-AF030080	Paper Feed Roller: Pick-up	1 - 1	~/~	'	20	*
AF031064 -		Feed Roller	1 - 1	X/X	7	32	**
	– AF031081	Paper Feed Roller: Feed: Manual Feed	1 - 1	~/~	'	32	**
AF032050 -		Separation Roller	1 - 1	X/X	9	4	**
	- AF032080	Paper Feed Roller: Separate	1 - 1	~/~	9	4	**

Note * and **: as a set O/O

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
RT44	120/60	USA, Canada, S. America	B587-17	J5430100001
RT44	220-240/50, 60	Europe, Asia, Oceania, etc	B587-26	2Q50130001
RT44	220-240/50, 60	Europe, Asia, Oceania, etc	B587-27	J5430100083

RIGOH

Modification Bulletin

Model: LCT for Moji	to-C2	e: 12-Feb-0	4	No.: MB587002					
Modified Article: S	eparation Torque Limiter		Prepared by: F.Noguchi						
From: 2nd Tech. Su	pport Sec. Service Support De								
Reason for	Parts catalog correction	U Venc	Vendor change			neet standards			
Modification:	To facilitate assembly	To improve reliability			()			
	Part standardization								

The following has been changed due to parts standardization with the Martini.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2472900 -		Separation Torque Limiter	4 4	0/0	9	5	
	– B0656399	Torque Limiter	1 - 1	0/0	9	5	

RIGOH

Modification Bulletin

Model: LCT for Moji	to-C2	Date	e: 17-Jun-04	4	No.: MB587003			
Modified Article: S	eparation Torque Limiter		Prepared by: F.Noguchi					
From: 2nd Tech. Su	pport Sec. Service Support De							
Reason for	Parts catalog correction	U Vend	lor ch	ange	🗌 To m	neet standards		
Modification:	To facilitate assembly	🗌 To in	To improve reliability)		
	Part standardization							

The following has been changed due to parts standardization.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0656399 -		Torque Limiter	4 4	0/0	0	Б	
	– A2946700	Torque Limiter - 53MNXM	1 - 1	0/0	9	5	

RICOH

Part Change Information List

		PCIL	PCIL	Old	New											
Model	Code	Number	Correction	part number	part number		Description	Old Q'ty	New Q'ty Int	3DPC	Page	Index	Set Set	Int RTB	Note	Ref Number
Mojito LCT for C2 (OAHU)	B587	200903		AW010048	AW010106	PAPER FEED SENSOR		1	1 0/0		7	3	3			V0804408

Date: March 18, 2009



Part Change Information List

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number		Description	Old Q'ty	New Q'ty	Int 3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.
M-C2 LCT	B587	200907		A3802280	B4732280	PICK-UP SOLENOID		1	1	0/0	7	19)				V0900705

Date: July 31, 2009