

Model: MT-C5 LCIT RT4040		Date: 1-Aug-17	No.: RD613001
Subject: Part Catalog Correction: Table		Prepared by: K. Moriizumi	
From: 1st Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	☒ Part information ☐ Electrical ☐ Transmit/receive ☐ Other ()	☐ Action required ☐ Service manual revision ☐ Retrofit information ☐ Tier 2 ☐ Tier 0.5

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	D7091750	Table: Large Capacity Tray: Ass'y	1	-	9	*	
B4731785	B4731786	Table	1	XX	9	21	A
B4731756	D7091754	Front Bracket - Timing Belt	1	XX	9	23	A
B4731757	D7091755	Rear Bracket - Timing Belt	1	XX	9	15	A
07403808	08053575	Ball Bearing - 8x16x5mm	1	XX	9	111	A
A3801752	-	Roller Shaft	4 -> 0	-	9	16	A
0720 0060E	-	Retaining Ring - M6	4 -> 0	-	9	110	A
-	D7091756	Spacer: Paper Tray	0 -> 2	-	9	24	A
-	04524016E	Binding Self – Tapping Screw: 4x16	0 -> 2	-	9	112	A

Note:

A: Interchangeability of combination parts: O/O

The first time that you replace any of these parts, make sure to install all the new parts as a set at the same time.

Change/Reason:

To prevent the table from slanting.

