

Model: MT-C4	Date: 24-Feb-10	No.: RD062034
--------------	-----------------	---------------

Subject: EPROM: PCB: Maui		Prepared by: K.Yamamoto	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

This RTB is for the reissue of MB473012

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4735110	B4735142	PCB:MAUI:ASS'Y	1	X/O	17	*	
B4735153	B4735155	PROM: PCB: Maui	1	X/O	17	1	

Change/ Reason: Firmware modified to support the Martini-C4 series.