

Model: Triton-C1 LCT (RT47)		Date: 2-Aug-05	No.: MB725001
Modified Article: Roller		Prepared by: M. Tsuyuki	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change/Reason: Please delete these parts from your Parts Catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index
B7251306		Roller (4401964420)	1 → 0		9	6
B7251330		Roller (4401964280)	1 → 0		9	30



Part Change Information List

Date: Jun 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	3	3	O/O		3	20					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	22	22	O/O		5	23					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	6	6	O/O		7	12					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	10	10	O/O		9	46					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	6	6	O/O		11	5					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	6	6	O/O		13	51					V1000195	
TR-C1 LCT (RT47)	B725	201006		B1867009	B1869716	TAPPING SCREW - M3X6(X0-02592000)	6	6	O/O		15	22					V1000195	