RICOH

Modification **B**ulletin

RICOH	M odification B ulletin				PAGE: 1/1	
Model: Model U-C	Da	Date: 1-Jun-07		No.: MB510001		
Modified Article:		Prepared	Prepared by: H.K.			
From: Technical S	Service Dept., GTS Division					
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization		J	☐ To n	neet standards)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5105472	B5105474	HARNESS:SHIFT TRAY	1	0/0	3	8	

Due to vendor change, the part number has been changed.

RICOH

Reason for

Modification:

Model: Model U-C1/TH-C1 Shift Tray

Modified Article: STB PCB & Motor Harness
From: Technical Service Dept., GTS Division

Modification Bulletin

Date: 15-Jun-07			No.: MB510002		
	Prepared	by: H.	ζ.		
☐ Vendor cha☐ To improve	· ·	⊠ To n (Ro	neet standards HS)		

PAGE: 1/2

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B3135252	B4595252	HARNESS - STB MOTOR	1	X/O	3	9	
B3135164	B4595165	PCB:STB	1	X/O	3	3	

☐ Other

Change: The materials for these parts were changed.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Reason: To comply with the RoHS Directive.

Note:

The functions of these parts were not changed.

IMPORTANT:

The materials for the parts were changed before the part numbers were changed.
 To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts Parts with the **new** P/N: **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	OK	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until
 the stock of these parts runs out. Then, start using RoHS compliant parts on the
 non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification **B**ulletin

Model: Model U-C1/TH-C1 Shift Tray

Date: 15-Jun-07

No.: MB510002

PAGE: 2/2

[RAI (China) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Ricoh/NRG/Lanier Internal Shift Sort Tray Type 1232	110,120,220,230 ,240/50,60	USA, Europe, Asia, etc	B510-17	Spare parts only
Infotec Internal Shift Sort Tray Type 1232	110,120,220,230 ,240/50,60	Europe	B510-26	Spare parts only
Ricoh/NRG/Lanier Internal Shift Sort Tray Type 3232	110,120,220,230 ,240/50,60	USA, Europe, Asia, etc	B510-27	J3066300001
Infotec Internal Shift Sort Tray Type 3232	220,230,240/50, 60	Europe	B510-66	2S88360001