

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Internal Shift Tray SH3050	D583	201112		B7914455	D6334455	LEVER:TORQUE LIMITER:SHIFT TRAY	1	1	O/O	201203-02							V1103227	11110017



Part Change Information List

Date: April 27, 2012

Model	Code	PCIL No.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. No.	ECN No.
Internal Shift Tray SH3050	D583	201202		D3334455	D6334455	CAM-SHIFT TRAY	1	1	X/X	201203-01			A		RD583001		V1103227	11110017
Internal Shift Tray SH3050	D583	201202		B7914455	D6334455	TORQUE LIMITER LEVER	1	1	X/X	201203-02			A		RD583001		V1103227	11110017



Part Change Information List

Date: October 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Internal Shift Tray SH3050	D583	201407	Canceled		D5834771	BASE:MAIN:ARAL-G	0	1		No						This information was incorrect.	V1401685	