

Model: Internal Shift Tray (SH3040)		Date: 24-May-12	No.: RD388001
Subject: Parts change information.		Prepared by: H. Tamaki	
From: 1st Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other (      ) <input type="checkbox"/> Tier 2		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7914455	D6334455	LEVER:TORQUE LIMITER:SHIFT TRAY	1	X/X As a set	-	-	-
D3884651	D6334651	CAM:SHIFT TRAY	1		-	-	

**Change:**

The shapes of the lever and the cam were changed to optimize the torque.