Model: SP5/SP5L Printer Control Unit Date					9	No.: MA852001		
Modified Article: Printer Control Board					Prepared by: A. Sasaki			
From: Technical Services Dept., GTS Division								
Reason for	☐ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability			(	)		
	☐ Part standardization	Othe	Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A852 5120—	Ī	Printer Controller	1		3	13	
	<sup>—</sup> A852 5300	Printer Control Board Ass'y (Others)	1	X/O	3	13	
A852 5120 —	ī	Printer Controller	1		3	13	
	<sup>L_</sup> A852 5355	Printer Control Board Ass'y (Lanier)	1	X/O	3	13	

The old printer control board contains a blank flash ROM (no firmware).

So, it has been changed to an assembly that includes firmware in the flash ROM. The assembly consists of the parts as shown.

