

Model: Model AT-C1 Finisher (SR3010)		Date: 28-Jan-09	No.: MB792001
Modified Article: PCB Board		Prepared by: M.Kumagai	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7925000	B7925100	PCB: PF4143K300	1	O/O	19	16	
B7923034	B7923134	Harness: PF4143K330	1	X/O	19	20	

Change/Reason: Parts standardization with the **D043**.



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Finisher SR3010 for PR-C1	B792	201005		B7923034	B7923134	Harness:PF4143K330	1	1	O/O		19	20					T0701264	7031576

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 Finisher (SR3010)	B792	201009			B7921028	SPACER:PF4143P014	0	1			20	28			RB792003		V1001960	10081118
AT-C1 Finisher (SR3010)	B792	201009			B7921027	SPACER:PF4143P013	0	2			20	29			RB792003		V1001960	10081118



Part Change Information List

Date: December 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 Finisher (SR3010)	B792	201112		B7924080	B7924082	DC MOTOR:4H5-0406-000	1	1	O/O		15	12					V1101164	11041222