

Model: Adonis-C2 Two Tray Finisher		Date: 26-Jun-01	No.: RB003007
Subject: Software Release Information		Prepared by: S. Tomoe	
From: Technical Services Dept., GTS Division			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other (       )		

## Software history

B3525701	Version	C. SUM
B	4.10	27C8

Symptom Corrected	Suffix
When one of the trays is full and paper is fed to the other tray, the tray does not lower.	B
When the door is opened soon after a staple job has finished, the finisher does not signal the copier that there is paper in the staple tray.	B
Corrects the suffix of the finisher software part number that is displayed on the LCD with the SP mode.	B
Wrong: B3525701P -> Correct: B3525701A	