

Model: Bellini-C2 Finisher (SR841)		Date: 8-Sep-04	No.: MB706001
Modified Article: Pawl Stopper Open And Close Bracket		Prepared by: M. Matsuda	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6744526	B7064526	Pawl Stopper Open And Close Bracket	1	X/O	9	32	

Changed: Material

Reason: To increase latitude against peeling from contact with the stripper pawl.

[RCL (Japan) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K3140300001
	220-240/50, 60	Europe(Danka)	B706-26	5C30440001

Model: Bellini-C2 Finisher (SR841)		Date: 8-Sep-04	No.: MB706002
Modified Article: Pawl Stopper Motor Bracket		Prepared by: M. Matsuda	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6744619	B7064619	Pawl Stopper Motor Bracket	1	X/O	9	12	

Changed: Part number only

Reason: Parts control

NOTE: The old bracket was used on the SR841 and SR860. The new one is only for the SR841.

[RCL (Japan) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K3140300001
	220-240/50, 60	Europe(Danka)	B706-26	5C30440001

Model: Bellini-C2 Finisher (SR841)		Date: 8-Sep-04	No.: MB706003
Modified Article: Decal:misfed Removal:paper		Prepared by: M. Matsuda	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4787020	B7067020	Cover:Front:Sub-ass'y	1	X/O	7	15	
B4787721	B7067721	Decal:misfeed Removal:Paper	1	X/O	7	17	

Changed: Illustration on decal for removing misfeed
Reason: This finisher can handle output from a Z-fold unit

[RCL (Japan) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K3140300001
	220-240/50, 60	Europe(Danka)	B706-26	5C30440001

Model: Bellini-C2 Finisher (SR841)		Date: 19-Nov-04	No.: MB706004
Modified Article: TRAY:AUXILIARY		Prepared by: M.Matsuda	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0391321	HOLDER:OPERATING INSTRUCTIONS:A5-NRC:ASS'Y	1		7	*37	
	B7067621	TRAY:AUXILIARY:PROOF TRAY	1		7	*38	
	B7067631	TRAY:AUXILIARY:SHIFT TRAY	1		7	*39	

*: New Index

Change: Parts added.

Reason: To improve paper stack accuracy for Z-fold paper.



B0391321 HOLDER:OPERATING INSTRUCTIONS:A5-NRC:ASS'Y



Proof Tray



B7067621 TRAY:AUXILIARY:PROOF TRAY



Shift Tray



B7067631 TRAY:AUXILIARY:SHIFT TRAY

Model: Bellini-C2 Finisher (SR841)		Date: 19-Nov-04	No.: MB706005
Modified Article: Jogger Fence		Prepared by: M.Matsuda	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3024611	B7064611	JOGGER FENCE:FRONT:ASS'Y	1	X/O	13	12	
	B7064631	GUIDE:JOGGER FENCE:FRONT	1		13	*24	

*: New Index

Change: Guide added, assembly P/N changed.

Reason: To further improve the accuracy of the jogger fence.



(Image from front side)

B7064611 GUIDE: JOGGER FENCE: FRONT: ASS'Y

B7064631 GUIDE: JOGGER FENCE: FRONT



(Image from rear side)

Model: Bellini-C2 Finisher (SR841)		Date: 20-Dec-04	No.: MB706006
Modified Article: Exit Guide Plate		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☒ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3024712	B4784712	GUIDE PLATE:STAPLER TRAY	1	X/O	13	14	
B3021124	B4781134	SUPPORTING PLATE:FRAME	1	X/O	47	15	
B3021194	B4781192	BRACKET:COUPLING:UPPER	1	X/O	33	9	
B4784411	B4784412	SIDE PLATE:REAR:STAPLER:ASS'Y	1	X/O	17	4	
B4781141	B4781143	BRACKET:COUPLING:GROUN D PLATE:FRONT	1	X/O	7	22	
B3024312	B4784311	SIDE PLATE:FRONT:STAPLER	1	X/O	17	18	
B3024749	B4784749	STAY:STAPLER:MIDDLE	1	X/O	13	9	
B3026612	B4786612	INNER COVER:FRONT	1	X/O	7	14	
B3026651	B4786651	INNER COVER:STAPLER UNIT	1	X/O	11	1	

Change/Reason: Parts standardization with the Victoria and Victoria-B.

Model: Bellini-C2 Finisher (SR841)		Date: 20-Dec-04	No.: MB706007
Modified Article: Standard Fence		Prepared by: S.Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☒ To improve reliability	
	☐ Part standardization	☐ Other	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4784531	B7064531	Standard Fence: Rear: Auxiliary: Ass'y	1	X/O	15	8	

Change: The attachment position of the rear standard fence was changed.

Reason: To improve stapling accuracy.

Model: Bellini-C2 Finisher (SR841)		Date: 8-Feb-05	No.: MB706008
Modified Article: Harness:motor		Prepared by: S.Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4785220	B4785221	HARNESS:MOTOR:SHIFTTRAY	1→1	X/O	43	36	
B4785466	B4785467	HARNESS:MOTOR CONTROL:SHIFT:JOGGER	1→1	X/O	43	29	
B4785370	B4785371	HARNESS:MOTOR:STAPLE TRAY	1→1	X/O	43	35	

Changes:

- 1) B4785220 → B4785221: The length was increased from 280mm to 300mm, and insulating tape was added.
- 2) B4785466 → B4785467: The length was increased from 580mm to 600mm, and insulating tape was added.
- 3) B4785370 → B4785371: The harness binder was moved closer to the PCB connector.

Reason: Parts standardization with the Victoria-B.

[RCL (Japan) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K3140300001
	220-240/50, 60	Europe(Danka)	B706-26	5C30440001

Model: Bellini-C2 Finisher (SR841)		Date: 26-Apr-05	No.: MB706009
Modified Article: PCB:Main Control		Prepared by: S.Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7065131	B7065132	PCB:Main Control	1	X/O	43	17	
B7065106	B7065107	Eprom:Main Control:Combination For Rom	1	X/O	43	40	

Change/Reason: The software for the SR841 finisher was changed.

Note: For details, see the SR841 firmware release note.

[RCL (Japan) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K3140900001
	220-240/50, 60	Europe(Danka)	B706-26	5C30840058

Model: Bellini-C2 Finisher (SR841)		Date: 14-Jul-05	No.: MB706010
Modified Article: Photo Reflection Sensor		Prepared by: S.Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Incorrect Part Number	Correct Part Number	Description	Q'ty	Page	Index	Note
AW020086		Photointerruptor	1	15	38	
	AW010091	Photo Reflection Sensor	1	15	38	

Change/Reason: The P/N and description were corrected.

Model: Bellini-C2 Finisher (SR841)		Date: 26-Aug-05	No.: MB706011
Modified Article: Parts Catalog Correccion		Prepared by: S. WATANABE	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change/Reason: The following index numbers were corrected.

Pg. 3

Part number	Description	Old index	New Index	Note
B5132110	Jogger Fence: front ass'y	18	23	
B5132120	Jogger Fence: inner back ass'y	23	18	

Model: Finisher SR841		Date: 11-Aug-06	No.: MB706012
Modified Article: Main Board and EPROM on SR841		Prepared by: H. Matsui	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7065132	B7065200	PCB: MAIN CONTROL	1-1	X/O	43	17	
B7065107	B7065213	EPROM: MAIN CONTROL	1-1	X/O	43	40	

Change: The parts in the table were changed to parts used on the SR842.

Reason: The SR841 finisher was discontinued.

Note:

1. P/N B7065200 includes P/N B7065213 (EPROM).
2. An SR841 finisher can be upgraded to an SR842 by replacing the PCB: MAIN CONTROL with the new part above (B7065200).

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 29-Aug-06	No.: MB706013
Modified Article: PCB:SHIFT:JOGGER		Prepared by: S.Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX040096	AX040139	STEPPER MOTOR:MM42:0.95A:9.5V	1	O/O	3	9	
AW020086	AW020156	PHOTOINTERRUPTOR	2	O/O	3	5	
B5135100	B8305120	PCB:SHIFT:JOGGER	1	O/O	3	8	
B5135210	B8305282	HARNESS:MOTOR:SHIFT:JOGGER:OPTION	1	O/O	3	7	

Change: Materials change.

Reason: Ricoh's ongoing changes toward more environmentally-friendly materials

[RCL (Japan) Production]


MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
SR841	208-240/50,60	USA, Europe, etc	B706-17	K31ymmxxxxx
	220-240/50, 60	Europe(Danka)	B706-26	5C3mmyxxxxx

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 5-Dec-06	No.: MB706014
Modified Article: Parts Catalog Correction(Timing Pulley)		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Product Safety	☐ Other ☐ To meet standards ()

Reason/Change: The part index in the following illustration is modified.

Incorrect Index	Correct Index	Part Number	Description	Q'ty	Page
5	12	B3021517	Timing Pulley 20Z	1	41

18.DRIVE SECTION (B706)



Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 10-Jul-07	No.: MB706015
Modified Article: PCB:MAIN CONTROL		Prepared by: T. Kiyohara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS Compliant) ☐ Part standardization ☐ Product Safety		

Change: The material of this part was changed.

Reason: To comply with the RoHS Directive.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7065200	B7065210	PCB: MAIN CONTROL	1	X/O	43	17	

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 25-Jun-08	No.: MB706016
Modified Article: Exit Guide Plate		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4784712	B4784713	GUIDE PLATE:STAPLER TRAY	1	X/O	13	14	

Change: Shape of the tray

Reason: To improve reliability.

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 23-Jul-08	No.: MB706017
Modified Article: Stripper Pawls:Open And Close:Ass'Y		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4783100	D4603100	Exit Roller Cover	1	O/O	37	4	
B4783107	D4603107	End Fence: Ass'y	1	O/O	37	16	
B4784261	D4604261	Slider: Base: Stapler: Ass'y	1	O/O	17	23	
B4782333	D4602333	Guide Plate: Exit: Lower: Sub-ass'y	1	O/O	35	22	

Change/ Reason: Parts standardization with the next model

Reissued:27-Jan-09

Model: Finisher SR841	Date: 3-Dec-08	No.: MB706018a
-----------------------	----------------	----------------

MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: Base Plate-Staple Hopper Holder		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for	☐ Parts catalog correction	☐ Vendor change	☒ Other
Modification:	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

21. FRAME SECTION 2 (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3021174	D4601174	Base Plate-Staple Hopper Holder	1	X/O	47	6	-
B4782131	D4602131	Bracket-Rear Upper Stay	1	X/O	43	19	-
B4784749	D4604749	Stay:Stapler:Middle	1	X/O	13	9	-

MB Cancellation
This MB#MB706018 has been cancelled.
Please ignore the parts number change information listed above.

Model: V-C1 Finisher (SR841)		Date: 11-Dec-08	No.: MB706019
Modified Article: Harness		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

19. ELECTRICAL SECTION (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4785310	D4605310	Harness:Paper Exit:Stapler Tray	1	X/O	43	15,38	-
B4785380	D4605380	Harness:Solenoid:Exchange Powl	1	X/O	15	25	-
B4785380	D4605380	Harness:Solenoid:Exchange Powl	1	X/O	43	10	-
B4785431	D4605431	Harness:Motor:Return	1	X/O	39	2	-

Model: SR841		Date: 7-Jan-09	No.: MB706020
Modified Article: Harness: Interface		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

19. ELECTRICAL SECTION (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4785201	D4605201	Harness: Interface: Ass'y	1	X/O	43	9	-

Change: The material of this part was changed.

Reason: To comply with the RoHS Directive.

Model: SR841 Finisher		Date: 13-Jan-09	No.: MB706021
Modified Article: Guide Plate - Punch Unit		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

8. STAPLE TRANSPORT 1 (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A6972160	D4602160	Guide Plate - Punch Unit	1	X/O	21	6	-

Model: Bellini-C2/Model V-C1 Finisher		Date: 15-Jan-09	No.: MB706022
Modified Article: Gathering Roller: Sponge		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4783503	B8303503	Gathering Roller: Sponge	2	O/O	39	26	

Change/ Reason: Parts standardization

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 02-Feb-09	No.: MB706023
Modified Article: Harness: Interface: Ass'y		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4785201	D4605201	Harness: Interface: Ass'y	1	O/O	43	9	

Change/ Reason: Part standardization.

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 05-Feb-09	No.: MB706024
Modified Article: Cover: Jogger		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☒ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

JOGGER UNIT (B513)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5131171	B5131175	Cover: Jogger	1	X/O	3	19	

Change: The shape of this part was changed.

Reason: To facilitate assembly.

Reissued:24-Feb-09

Model: Model V-C1 Finisher SR841	Date: 23-Feb-09	No.: MB706025a
----------------------------------	-----------------	----------------

MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: BRACKET:PHOTO REFIECTION SENSOR:OVERFLOW		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

12. TRANSPORT SECTION 1 (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7062246	D4602245	BRACKET:PHOTO REFIECTION SENSOR:OVERFLOW	1-1	X/O	29	16	-
04513012N	03130080N	PAN HEAD SCREW:M3X8	1-1	X/O	29	107	-

Model: Bellini-C2/Model V-C1 Finisher (SR841)		Date: 25-Feb-09	No.: MB706026
Modified Article: Interlock Switch		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

20. FRAME SECTION 1 (B706)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
12042384	12042848	Interlock Switch	1-1	X/O	45	105	-



Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B5452019	B8041035	CASTER:DIA50:400N	4	4	O/O		47	17					V0803305
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		A6973205	D4603205	BRACKET:PHOTOINTERRUPTOR:SHIFT	1	1	O/O		37	13					V0803530
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B4783121	D4603121	EXIT STAY	2	2	X/O		37	15					V0803530
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B7065440	D4605440	HARNESS:SENSOR:RETURN:SURFACE OF PAPER SENS	1	1	O/O		37	*23			Y		V0803530
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		A6972160	D4602160	GUIDE PLATE:AUXILIARY:PUNCH:ASS'Y	1	1	X/O		21	6					V0804293
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B8305201	D4605201	HARNESS:INTERFACE	1	1	O/O		43	9					V0804540
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B3021174	D4601174	BASE:HOLDER:TONER HOPPER:ASS'Y	1	1	X/O		47	6					V0804483
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B4782131	D4602131	BRACKET:STEPPER MOTOR:ASS'Y	1	1	X/O		47						V0804483
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B4784749	D4604749	STAY:STAPLER:MIDDLE	1	1	X/O		47						V0804483
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904		B3024717	B7064785	SHAFT:EXIT:UPPER	1	1	X/O		15	20	A		Y		V0804692
Bellini-C2/Model V-C1 Finisher (SR841)	B706	200904			B4784782	BRACKET:EXIT:UPPER	0	1			15	40	A		Y		V0804692





Part Change Information List

Date: May 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
B-C2/V-C1 Finisher (SR841)	B706	200905		B4786211	D4606211	COVER:REAR	1	1	X/O		7	1					V0900578
B-C2/V-C1 Finisher (SR841)	B706	200905		B6744521	B8304889	TIMING BELT - 40S2M500	1	1	O/O		9	4					V0900387
B-C2/V-C1 Finisher (SR841)	B706	200905		B3024517	D4604518	PLATE:TRAILING EDGE	1	1	X/O		15	6					V0900586
B-C2/V-C1 Finisher (SR841)	B706	200905		B7062246	D4602245	BRACKET:PHOTO REFLECTION SENSOR:OVERFLOW	1	1	X/O		29	16					V0900581
B-C2/V-C1 Finisher (SR841)	B706	200905		B7065440	D4605440	HARNES:SENSOR:RETURN:SURFACE OF PAPER SENSOR	1	1	O/O		37	12					V0804416
B-C2/V-C1 Finisher (SR841)	B706	200905		B3023220	AA043637	TIMING BELT - 40S2M124	1	1	O/O		37	7					V0900387
B-C2/V-C1 Finisher (SR841)	B706	200905		B4783554		GUIDE:FEELER:PAPER SENSER	1	0	O/X		39	36					V0901001
B-C2/V-C1 Finisher (SR841)	B706	200905		B4783552	B4783555	FEELER:PAPER SENSER		1	O/X		39	11					
B-C2/V-C1 Finisher (SR841)	B706	200905		B4781137	D4601137	COVER:SAFETY SWITCH	1	1	O/O		45	17			Y		V0900549
B-C2/V-C1 Finisher (SR841)	B706	200905			D4601146	COVER:HARNES:DOOR SWITCH	0	1			45	19			Y		V0900549



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	200906		B4784713	B4784714	GUIDE PLATE:STAPLER TRAY	1	1	X/X		13	14			Y		V0900376	8121308
B-C2/V-C1 Finisher (SR841)	B706	200906			B8304783	BRACKET:EXIT:UPPER	1	1	X/O		13	25			Y		V0900376	8121308
B-C2/V-C1 Finisher (SR841)	B706	200906		B4605440	AW020156	PHOTOINTERRUPTOR:EE-SX4235A-P2	1	1	X/O		17	12						
B-C2/V-C1 Finisher (SR841)	B706	200906		AW010091	AW010129	PHOTO REFIECTION SENSOR	1	1	X/X		29	14	A	X/O	Y		V0900581	8071165
B-C2/V-C1 Finisher (SR841)	B706	200906		B7062246	D4602245	BRACKET:PHOTO REFIECTION SENSOR:OVERFLOW	1	1	X/X		29	16	A	X/O	Y			



Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	200908		B3022217	B7062216	Entrance Guide - Upper Exit Guide	1	1	X/O		29	10						
B-C2/V-C1 Finisher (SR841)	B706	200908		B3023212	D4603214	BRACKET:SHIFT:ASS'Y	1	1	X/X		37	10	A	X/O	Y		V0902075	9070503
B-C2/V-C1 Finisher (SR841)	B706	200908		AX050277	AX050323	DC Motor - 24V -9.9W	1	1	X/X		37	11	A	X/O	Y			
B-C2/V-C1 Finisher (SR841)	B706	200908			D4603402	DRIVE SUB-UNIT:SHIFT:ASS'Y		1	-		37	25*			Y			



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	200910		D4604518	D4604538	PLATE:TRAILING EDGE	1	1	O/O		15	6					V0901298	9041118



Part Change Information List

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201002		B4784714	B4784715	GUIDE PLATE:STAPLER TRAY	1	1	O/O		13	14					V0902298	9070929
B-C2/V-C1 Finisher (SR841)	B706	201002		A6972160	D4602160	GUIDE PLATE:AUXILIARY:PUNCH:ASS'Y	1	1	X/O		21	6					V0903265	



Part Change Information List

Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201004		B7064785	B7064786	SHAFT:EXIT:UPPER	1	1	O/O		15	20					V0902298	9070929
B-C2/V-C1 Finisher (SR841)	B706	201004		B8304783	B8304784	BRACKET:EXIT:UPPER	1	1	O/O		15	40					V0902298	9070929
B-C2/V-C1 Finisher (SR841)	B706	201004		B3022124	D4602124	BRACKET:GATHERING ROLLER	1	1	X/X		27	17	A		RB706006		V1000603	8120495
B-C2/V-C1 Finisher (SR841)	B706	201004		B4782111	D4602111	ARM:GATHERING ROLLER:ASS'Y	1	1	X/X		27	23	A		RB706006		V1000603	8120495



Part Change Information List

Date: January 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher(SR841)	B706	201101		B3024619	B4784619	JOGGER FENCE SHAFT	2	2	O/O		13	17					10502324	



Part Change Information List

Date: May 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201105		B3024248	D4604248	HOLDER:MIDDLE:STAPLER:ASS'Y	1	1	O/O		25	3					V1100829	11030856





Part Change Information List

Date: June 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201106		B4782333	D4602333	GUIDE PLATE:EXIT:LOWER:SUB-ASS'Y	1	1	O/O		35	22					V1100404	



Part Change Information List

Date: August 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201108		D4606211	D4606213	COVER:REAR	1	1	O/O		7	1					V0902426	09080801
B-C2/V-C1 Finisher (SR841)	B706	201108		B4785400	D4605402	HARNESS:STAPLER	1	1	O/O		43	14					V1100829	11030856



Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201110		B4782243	B8302243	END PLATE:UPPER:EXIT:PROOF TRAY	1	1	X/O		29	18					V1102423	10120054



Part Change Information List

Date: June 29, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201206		D4602124	D4602127	BRACKET:GATHERING ROLLER	1	1	X/O		27	17					V1200776	12030054



Part Change Information List

Date: September 28, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/V-C1 Finisher (SR841)	B706	201209		D4603107	D6103107	END FENCE	1	1	X/O		37	16					V1201851	12071415



Part Change Information List

Date: May 31, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2/V-C1 Finisher (SR841)	B706	201305		B4786212	D4606213	COVER:REAR	1	1	O/O		7	2					V1300023	



Part Change Information List

Date: January 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2/V-C1 Finisher (SR841)	B706	201401		B4786262	D4606262	COVER:COVER:LEFT UPPER	1	1	O/O		7	30					V1300600	13020357



Part Change Information List

Date: February 28, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2/V-C1 Finisher (SR841)	B706	201402		B7063172	D4603172	ACTUATOR BRACKET	1	1	O/O		35	10					V1300600	13020357



Part Change Information List

Date: February 27, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2/V-C1 Finisher (SR841)	B706	201502		B7062224	B8302224	COMPRESSION SPRING:TRANSPORT:6.5N	2	2	X/O		23	5					V1403408	14091170
B-C2/V-C1 Finisher (SR841)	B706	201502		B4781137	D4601137	COVER:SAFETY SWITCH	1	1	X/O		45	17					V0901244	



Part Change Information List

Date: February 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2_V-C1 Finisher_SR841_	B706	201701		AA120099	B7002317	DISCHARGE BRUSH	1	1	O/O	N	27	10					V1700043	16121056