

Notes for Users

When using ES-2000 to measure a calibration chart printed using the auto calibration function, make sure to measure it by sliding ES-2000 from left to right in the order of the line numbers displayed on the screen.

Pay attention to which measurement direction should be specified as specifying a wrong measurement direction does not result in adequate measurement results.

© 2018

Printed in Japan

EN(GB)EN(US)EN(AU) M521-6901



M5216901