16	回	П
ルりし		뮈

PAGE: 1/1

Model: Pomelo			Date	e: 30-Apr-99	9	No.: MG033001
Modified Article: Parts Catalog			Prepared	by: H.	Someya	
From: Technical Se	ervice Dept., GTS Division					
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization	☐ Vend☐ To in☐ Othe	nprove	ange e reliability	☐ To n	neet standards)

Please correct your parts catalog as follows.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
V126176	V126528	Separation Pad			9	8	
V126176	V126528	Separation Pad			15	6	

ገጦጦ)[[]
	加儿


Model: Pomelo		Da	te: 30-Jun-9	9	No.: MG033002
Modified Article: Parts Catalog			Prepared	bу: н.	Someya
From: Technical Se	ervice Dept., GTS Division				
Reason for	☐ Parts catalog correction	☐ Vendor c	hange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
	☐ Part standardization	Other			

The following parts have been registered as service parts:

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
	V126534	Actuator – Transfer Unit	1		3	11	*1
	V126531	Wedge – 3 pcs	1		3	12	*1
	V126529	Oil Felt – Fusing Roller	1		9	33	*1
	V126530	Oil Pan Unit	1		9	34	*1
	V126533	Quenching Lamp Holder – 2 pcs	1		9	35	*1
	G0296845	Decal – Aficio *2	1		17	5	*1

*1: New index, *2: Only used for the Europe version (G033-27)


PAGE: 1/2





PAGE: 2/2

Model: Pomelo Date: 30-Jun-99 No.: MG033002






PAGE: 1/	1
----------	---

Model: Pomelo Date			e: 15-Aug-9	9	No.: MG033003
Modified Article: Optical Unit				l by: H.	Someya
From: Technical Ser	vice Dept., GTS Division]		
Reason for	Parts catalog correction	☐ Vendor ch	nange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	□ To improve reliability		()
	☐ Part standardization	Other			

To prevent dust from entering the optical unit, polyester tape has been attached to block the holes in the base.

Old par		w part mber	Description	Qty	Int	Page	Index	Note
	V1:	26239 F	Polyester Tape – 20 pcs	1		9	36	

Note: The above part contains 20 pieces of tape (as one set).



MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Color Laser AP204	120/50,60	USA	G033-17	P0690200649
Gestetner C7004				
Savin SLP416c				
Ricoh Color Laser AP204	220/50,60	Europe	G033-27	P0690200869

Пι	\bigcirc	M	ПП
	G	(])	N

PAGE:	1/5
-------	-----

Model: Pomelo Date			e: 12-Jun-0	0	No.: MG033004
Modified Article:	Parts Catalog	Prepared	l by: н.	Someya	
From: Technical Se	ervices Dept., GTS Division				
Reason for	□ Parts catalog correction	☐ Vendor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
	☐ Part standardization	☐ Other			

The following parts have been registered as service parts:

New part	Description	Q'ty	Int	Page	Index	Note
number						
V126536	BC Wire Cleaner	1		3	13	
V126190	TR Regist Roller	1		3	14	
V126574	Paper Guide L (UP) 2	1		5	5	
V126534	Actuator – Transfer Unit	1		5	6	
V126539	S Plate Assy	1		7	25	
V126577	HP Idle Z17 (2)	1		7	26	
V126426	DE Hinge Arm	1		7	27	
V126180	BC Terminal	1		7	28	
V126185	Front Stay R	1		7	29	
V126186	Front Stay L	1		7	30	
V126427	DE Solenoid Assy	1		7	31	
V126192	F Lock Cover	1		7	32	
V126168	Belt Sensor	1		9	27	*1
V126188	Lower Waste Toner Feeder	1		9	37	
V126199	MD Gear Ass'y	1		9	38	
V126247	Paper Guide D – 2 pcs	1		9	39	
V126200	Left Cassette Guide	1		9	40	
V126201	Right Cassette Guide	1		9	41	
V126540	WT Holder Assy	1		9	42	
V126541	SW Button	1		9	43	
V126575	FUCR Gear	1		9	44	
V126576	FU Gear 33	1		9	45	


^{*1:} The index number of belt sensor in the illustration has been corrected.





PAGE: 2/5

Model: Pomelo Date: 12-Jun-00 No.: MG033004






Model: Pomelo

Modification **B**ulletin

Date: 12-Jun-00 No.: MG033004


PAGE: 3/5





PAGE: 4/5


Model: Pomelo Date: 12-Jun-00 No.: MG033004






PAGE: 5/5

Model: Pomelo Date: 12-Jun-00 No.: MG033004





RIGOH

Modification Bulletin

PAGE: 1/1

Model: Pomelo			Date: 29-Nov-00		0	No.: MG033005
Modified Article: MCTL board and development drive unit				Prepared by: H. Someya		
From: Technical Services Dept., GTS Division				•		
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To im		☐ To improve reliability		()	
	☐ Part standardization	⊠ Other				

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
V126187	V126535	MCTL Board	1	X/07 x/0	7	3	
V126162	V126246	Development Drive Unit	1	$X/X \rightarrow Y_0$	9	22	

The MCTL board has been modified to minimize the following:

- 1. Insufficient transfer in a band at the leading edge equivalent to one turn of the development roller.
- 2. Dark lines on the printout at each turn of the development roller
- 3. Jitter at about 50 mm from the leading edge

Concerning #3 (jitter), the development drive unit has also been modified. Please refer to RTB# RG033006 for details.

Note: The old development drive unit will continue to be available as a service part.

MCTL Board

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Color Laser AP204	120/50,60	USA	G033-17	P0690900001
Gestetner C7004				
Savin SLP416c				
Ricoh Color Laser AP204	220/50,60	Europe	G033-27	P0690900489

Development Drive Unit

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Color Laser AP204	120/50,60	USA	G033-17	P0691000001
Gestetner C7004				
Savin SLP416c				
Ricoh Color Laser AP204	220/50,60	Europe	G033-27	P0691000489

ിമ്പ	١ПП
[[[]])牊

PAGE: 1/1

Model: Pomelo (only for G033-27)			e: 29-Jan-01		No.: MG033006		
Modified Article: PSU and MCTL Board				Prepared by: H. Someya			
From: Technical Services Dept., GTS Division							
Reason for	Parts catalog correction	☐ Vendor cl	change				
Modification:	☐ To facilitate assembly☐ Part standardization	☐ To improv	e reliability	(EIV	ic)		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
V126146	V126441	Power Supply Unit – EU	1	X/X) _{Y/O}	9	11	
V126535	V126547	MCTL Board – EU	1	X/X J	7	3	

To meet the new EMC compliance requirements implemented from 2001, the PSU and MCTL have been changed.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Color Laser AP204	120/50,60	USA	G033-17	
Gestetner C7004				
Savin SLP416c				
Ricoh Color Laser AP204	220/50,60	Europe	G033-27	P0600900017

	_	
		ы
7	_	

PAGE: 1/1

Model: Pomelo Date			e:11-Jan-06)	No.: MG033007
Modified Article: F	P CASSETTE GUIDE	Prepared by: H.K.			
From: Technical Se	rvice Dept., GTS Division				
Reason for	☐ Parts catalog correction	☐ Vendor ch	nange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
	□ Part standardization	☐ Other			

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
V126200	V127467	FP CASSETTE GUIDE L2	1	O/O	9	40	

Due to parts standardization, the part number has been changed.