RIGOH

Technical Bulletin

Model: Model PG-1		Date: 8-Jun-0		5	No.: RJ003001		
Subject: Firmware Release History				Prepared by: Y. Ohtani			
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:	Troubleshooting	Part info	ormat	tion	Action	n required	
	Mechanical	Electric	al		Servic	e manual revision	
	Paper path	Transmit/receive		eive 🗌 Retrofit info		fit information	
	Other ()						

This RTB has been issued to announce firmware release information.

General Information

Firmware Version	Program No.	Effective Date
6.01	J0035130	April 2005 production

History

Service Card Version	Symptom Corrected			
6.01	Other changes: Print speed control is disabled for "High-Speed" mode. Note: As a result, the machine will not decrease the print speed in "High-Speed" mode, even under low-temperature, low-humidity conditions.			

Important Notes for When Installing This Firmware:

- This firmware is only for **Model P-G1**. It cannot be used on Model A-G1.
- Install this firmware via a **direct USB connection** between a PC and the printer. **Note:** This firmware cannot be installed via a network connection.
- Before you start the installation:
 - > Shut down all other foreground applications on the PC.
 - > Make sure that the printer main power is ON.
- If the installation fails, execute the ".exe" file again.

RICOH

Technical Bulletin

P 1

Model: All GelSprinter models		Date: 26-Aug-		-08	No.: RJ007024		
Subject: GJ analysis tool				Prepared by: Y.Murata			
From: 1st Tech.	Support Sec. Service Support I	Dept.					
Classification:	Troubleshooting	Part infe	ormat	tion	Action	n required	
	Mechanical	Electric	al		Servic	ce manual revision	
	Paper path	Transmit/receive		eive	Retrofit information		
	Other ()				Tier2		

Important Information about a New GJ Analysis Tool

• When a problem occurs in the field, please use the GJ analysis tool available from the Firmware Download Center. The tool is available for all GelSprinter products.

Model list:

G500/G700/G7500 GX3000/GX3050N/GX5050N GX2500/GX7000 GX3000S/GX3000SF/GX3050SFN

Please use this tool to provide information for problem analysis, instead of the SMC report.