


Safety Labels of This Machine

The following labels are attached on the motor close to the transfer belt.



DFT110

1. The motor in the recess of the transfer belt has overheated. Do not touch the parts which labels are put on. Otherwise, an injury might occur.

© 2015

Printed in Japan

EN (GB) EN (US) EN (AU)

M238-1048



M2381048