

Important Notice

When replacing a toner cartridge, fusing unit, transfer unit, or drum unit, do not stop halfway when pulling it out. Doing so may cause the printer to fall over.

© 2012

Printed in Japan

EN (GB) EN (US) EN (AU)

M124-8550



M1248550