

**Reissued: 02-Mar-15**

Model: PRIPORT FV-LT	Date: 13-Jan-09	No.: RC654001f
----------------------	-----------------	----------------

**RTB Reissue**

The items in bold italics have been corrected or added.

Subject: Firmware Release History		Prepared by: K. Yamamoto	
From: 1st Tech Service Sect., MFP/Printer Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

The RTB has been issued to announce the firmware release information for the **FV-Lt**.

**FIRMWARE MODIFICATION HISTORY**

C6545150	File Name	Version	Production	Availability of RFU
<b><i>G</i></b>	<b><i>C6545150G.bin</i></b>	<b><i>4.00</i></b>	<b><i>November 2014 production</i></b>	<b><i>Not available</i></b>
F	C6545150F.bin	3.01	October 2012 production	Not available
E	C6545150E.bin	2.01	April 2011 production	Not available
D	C6545150D.bin	2.00	September 2009 production	Not available
C	C6545150C.bin	1.04	March 2009 production	Not available
B	C6545150B.bin	1.03	March 2009 production	Not available
A	C6545150A.bin	1.02	1 <sup>st</sup> mass production	Not available

**Note: Definition of Availability of RFU via @Remote**
**"Available"** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

Symptom Corrected / Changes	Suffix
<b><i>Additional Model Information:</i></b> <b><i>The Platinum-D4 is now supported.</i></b>  <b><i>Important:</i></b> <ul style="list-style-type: none"> <li><b><i>The memory capacity of the SD card must be 1G or less.</i></b></li> <li><b><i>Create a folder in the SD card directory called "ROMDATA", and then write/copy the firmware into this folder.</i></b></li> </ul>	<b><i>G</i></b>
Other changes: Supports Peridot-D1.	<b>F</b>
Symptom corrected: Wording errors (WIM display)	<b>E</b>


**Reissued: 02-Mar-15**

Model: PRIPORT FV-LT	Date: 13-Jan-09	No.: RC654001f
Other changes: 1. Supports the PT3. 2. Supports 300dpi printing.	D	
Other Change: Firmware modified to support the China model	C	
Other changes: Affected only Japanese products	B	
1st mass production	A	

Model: PT3		Date: 13-Nov-14	No.: RC275005
Subject: Parts catalog correction		Prepared by: A.Ishida	
From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

**Change/Reason:** The following accessories for the Printer Unit Type4545 (C654) for the PT3 were added to the Parts Catalog.

## Printer Unit Type4545 (C654)



Index	Part number	Description	Q'ty
1	C6545632	BRACKET:FVLT:LEFT UPPER	1
2	C6545640	BRACKET:FVLT:RIGHT LOWER	1
3	C6545631	BRACKET:FVLT:RIGHT UPPER	1
4	C6545633	BRACKET:WALL	1
5	C6545291	HARNESS:FVLT:DC POWER SUPPLY:ASS'Y	1
6	C6545290	HARNESS:FVLT:ASS'Y	1
7	C6545292	HARNESS:FVLT:GROUND WIRE:ASS'Y	1
8	16070623	FERRITE CORE - TFC-16-8-13	1
9	03530040N	SCREW - M3X4	5
10	04543006Q	TAPPING SCREW - M3X6	4
11	11050516	CLAMP	1