

Model: PRIPORT TITANIUM2		Date: 3-Oct-06	No: M-C261-002
Modified Article: Parts catalog correction for VC-20		Prepared by: K. Yamamoto	
From: Priport Service Planning Section			
Classification: <input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> To meet standards <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability () <input type="checkbox"/> Part standardization <input type="checkbox"/> Other ()			
Model Name: Ricoh JP735/JP755/JP785C, Gestetner 6123a+/6123b+/6123L+/6200C, Lanier LDD 735, nashuatec 6123a+/6123b+, RexRotary 6123a+/6123b+			

Note: This MB applies to the optional **Printer Unit VC-20.**

Index	Old #	New #	Description	Q'ty
1	C6465000	C6465010	CONTROL BOARD UC-2 ASS'Y	1

Change: The controller board was changed.

Reason: To support the Japanese display language.

