

Model: PRIPORT TITANIUM2		Date: 05-Jul-06	No: M-C261-001
Modified Article: VC-20 COMPONENT PARTS		Prepared by: M. Kanomata	
From: Priport Service Planning Section			
Classification: <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> To meet standards <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability () <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> Other ()			
Model Name: Ricoh JP735/JP755/JP785C, Gestetner 6123a+/6123b+/6123L+/6200C, Lanier LDD 735, nashuatec 6123a+/6123b+, RexRotary 6123a+/6123b+			

Note: This MB applies to the optional **Printer Unit VC-20.**

Index	Parts No.	Description	Q'ty
1	C6465000	CONTROL BOARD UC-2 ASS'Y	1
2	C6466000	IC DRIVER EXP ASS'Y	1
3	C6468650	SHEET INSTRUCTION MANUAL EXP	1
4	C6468651	SHEET ACCESSORY SAFETY EXP	1
5	04513006N	TAPPING SCREW - 3X6	3

Change: The parts in the table were added.

Reason: The optional Printer Unit VC-20 was newly released, and these are the option's individual service parts.

