

=====

*** Basic Information ***

=====

[Create date] 2018/10/26

[Program Name] Main

[Version] B14.2C

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AX5510B

[File Information]

File Name Y0AX5510B.exe

File Type Module for Service

Size 1.40 MB (1467770 byte)

Check Sum -8Bit Sum: A346

 -16Bit Sum(Little Endian): 62AB

 -16Bit Sum(Big Endian): 869B

[Availability of RFU] No

[Production reflection]

=====

*** Note ***

=====

[Note]

1)Additional Model Information

None

2)Specification Change

Support Remote controller ID setup

3>Error Correction

None

=====

*** Important Notes ***

=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

Support Remote controller ID setup

[Modification history]

Version B13.1C
Symptom corrected:
- Seldom need press power button twice to turn on the projector.

Version B11.1C
1st release